			. Ú	
Submi. 3 Copies to Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources Department		CISI	Form C-103 Revised 1-1-89
DISTRICT I OIL CONSERVATION DIVISION				
P.O. Box 1980, Hobbs, NM 88240	P.O. Box 2088		WELL API NO.	
<u>DISTRICT II</u> P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico 87504-2088		<u>30-015-22233</u> 5. Indicate Type of Lease	
DISTRICT III				STATE XX FEE
1000 Rio Brazos Rd., Aztec, NM 87410		~	6. State Oil & Gas Leas	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				
			7. Lease Name or Unit .	Agreement Name
1. Type of Weil: OL GAS WELL X WELL OTHER				
WEIL X WEIL 2. Name of Operator V	OTHER		Lakewood AQE State	
YATES PETROLEUM CORPOR	ATION	8. Well No.		
3. Address of Operator			9. Pool name or Wildcat	
105 South 4th St., Artesia, NM 88210			Wildcat Canyon	
4. Well Location				
Unit Letter :	J_ Feet From The North	Line and198	80 Feet From The	West Line
Section 30	Township 195 Rai	nge 26E	NMPM Eddy	
	10. Elevation (Show whether		NMPM Eudy	County
	3436	6' GR		
11. Check A	Appropriate Box to Indicate N	Nature of Notice, R	eport, or Other Dat	a
NOTICE OF INT			SEQUENT REPO	
	PLUG AND ABANDON	REMEDIAL WORK		
PULL OR ALTER CASING	CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB			
OTHER:		OTHER: Re-entry	Ž	X
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed				
work) SEE RULE 1103.				
12–25–99 – Moving in and rigging up rotary tools. 12–26–99 – Shut down for Christmas.				
12-27-99 - Finished moving in and rigging up rotary tools.				
12-28-99 - Welded on head and nippled up BOP. Tested BOP to 3000#. Drilled surface				
plug. Picked up drill collars - had to wash last 5 drill collars in hole. At report				
time - TD 472' - picking up drill collars. Spudded in at 2:00 AM 12-28-99. NOTE:				
Notified OCD-Artesia of re-entry.				
12-29-99 - TD 6230'. Washing to bottom. Picked up drillpipe and TIH. Tagged plug at 1393'. Tested casing to 1000# for 30 minutes, OK. Installed rotating rubber. Drilled				
plug from 1393-1437'. Washed stringers to 1656'. TIH to 3027'. Circulated at 3027'.				
TIH to 4332'. Circulated at 4332'. Pumped sweep. TIH to 5266'. Circulated. Washed				
from 5266-5422'. Circulate and condition mud. Washed from 5422-6230'.				
12-30-99 - TD 7189'.				
Drilled cement from 64				
I hereby certify that the information above is true and complete to the best of my knowledge and belief. CONTINUED ON NEXT PAGE:				
SKONATURE Tusty	4	<u>e</u> <u>Operations</u> Te	echnician p.	TE Jan. 12, 2000
TYPE OR PRINT NAME Rusty Klein			Ti	а <u>ерноне но. 505/748-1</u> 47
(This space for State Use) Jim W. Gum (1) Withit Supervisor				
		P		NTE / - 2/-C2
APPROVED BY	IIIL	-	<i>U</i> ,	

CONDITIONS OF APPROVAL, IF ANY: