	-	· · · ································	C:>
orm 9-331 May 1963) DEPAR	UNITED STATES	SURMIT IN TRIPLICATE* (Other instructions on re- Verse side)	Form approved. 2 udget Bureau No. 42-R142. 5. LEASE DESIGNATION AND SERIAL NO.
SUNDRY NO (Do not use this form for propulse "APPLI	GEOLOGICAL SURVEY	ON WELLS	NM-067896 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
OIL GAS WELL OTHER		14 1979	7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME
GULF OIL CORPORATION		C. C.	Keohane et al Federal 9. well NO.
P. O. Box 670, Hobbs, NM 88240 A. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface			10. FIELD AND FOOL, OR WILDCAT
1980' FNL	& 660' FEL		11. SEC., T., B., M., OB BLK. AND SURVEY OF AREA Sec 19-TL8S-R31E
I. PERMIT NO.	15. ELEVATIONS (Show whether p 3619* GL	F, RT, GR, etc.)	12. COUNTY OF PARISH 13. STATE Eddy NM
Check A NOTICE OF INTE		Nature of Notice, Report, or O	ther Data ENT REPORT OF:
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other)	PULL OR ALTER CASING	WATEB SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (Note : Report results	ALTERING WELL ALTERING CASING ABANDONMENT* of multiple completion on Well tion Report and Log form.)
from 10,700' to 10,49 8865' across 52" csg 5750'. Spotted 150' from 2100' - 1965'; 1 Mr. Jones, with USGS Installed dry hole ma ready for inspection.	27'. Cut 52" csg @ 9 stub. Spotted 150' p plug from 4600'-4450' 200' plug from 1200' witnessed plugging op arker. Removed tie do	plug from 7700' - 7550 ' across 9-5/8" csg sho to surface. Abandonme	cmt plug from 9100' to '; 150' plug f/5900' to pe. Spotted 135' plug ent mud between all plug te on 9-5/8" csg flange.
Work performed 4/10/7	9 to 4/22/79.		
	In this and convet		X
I hereby certify that the foregoing SIGNED	. ^	rea Engineer	

.....

0:5

See Instructions on Reverse Side