

SF/ files

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well gas well other

2. NAME OF OPERATOR

~~COOK OIL AND GAS PRODUCTION~~ Joe De...

3. ADDRESS OF OPERATOR

P.O. BOX 159, ROSWELL, N. MEX. 88201

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 2110 FSL + 250 TWD
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>		<input type="checkbox"/>
FRACTURE TREAT	<input checked="" type="checkbox"/>		<input type="checkbox"/>
SHOOT OR ACIDIZE	<input checked="" type="checkbox"/>		<input type="checkbox"/>
REPAIR WELL	<input checked="" type="checkbox"/>		<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>		<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>		<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>		<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>		<input type="checkbox"/>
(other)	<input type="checkbox"/>		<input type="checkbox"/>

5. LEASE
NM 3620

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
D.L. HANNIFIN fed. RECEIVED

9. WELL NO.
#1 01 12 1981

10. FIELD OR WILDCAT NAME
SHUGART

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
AREA 19S 31E, NMPM, Sect. 1
S $\frac{1}{2}$ N $\frac{1}{2}$ SW $\frac{1}{4}$, W $\frac{1}{2}$ SE $\frac{1}{4}$, SE $\frac{1}{4}$ SE $\frac{1}{4}$

12. COUNTY OR PARISH
EDDY

13. STATE
N. MEX.

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3617. GL


(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

NOVEMBER 5, 1981

PROPOSE TO:

- 1) DRILL OUT OR POUND PLUG AT 2819' to 2860'
- 2) SET NEW WIRELINE PLUG AT 2850'
- 3) SQUEEZE PERFS AT 2840-20 and 2806-11
- 4) DRILL OUT
- 5) REPERFORATE 2806-20
- 6) TREAT WITH 1500 GAL MCA ACID
- 7) IF GOOD EVALUATION CAN BE MADE - FRAC WITH 25,000 GAL 50% CO₂, 50% GEL WATER




Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE PRESIDENT DATE OCTOBER 23, 1981

APPROVED (This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL: ~~IF ANY~~



*See Instructions on Reverse Side