

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

MOCC COPY
SUBMIT IN TRIP
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Westall - Mask	8. FARM OR LEASE NAME Hinkle "B" Federal
3. ADDRESS OF OPERATOR P.O. Drawer 1477 Roswell, New Mexico 88201	9. WELL NO. 10.
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 330' FSL and 330' FWL	10. FIELD AND POOL, OR WILDCAT Shugart
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 27 - 18S - 31E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3616 GR.	12. COUNTY OR PARISH Eddy
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Drilled 3650'

2/7/78 3354-70, 3420, 3438, 3452,
3490-3506 - 46 Holes

40,000 Gals. Gelled Water
250 Gals. 15% DS-30
40,000 Lbs. 20/40 Sand

Ran rods and tubing, began producing 30 Barrels Per Day

8 5/8 20# Set at Depth 658 300 Sacks Cement

4 1/2 9.5# Set at Depth 3650 400 Sacks Cemer.

2 3/8 EUE Set at Depth 3500 Pumped 100 Sacks Cement down the Bradenhead

Total Depth Drilled 3,650'

Treatment Report attached.

18. I hereby certify that the foregoing is true and correct

SIGNED Jack Mask

TITLE Co-Owner

DATE 02/21/78

(This space for Federal or State office use)

APPROVED BY Joe S. Lara
CONDITIONS OF APPROVAL, IF ANY:

TITLE ACTING DISTRICT ENGINEER

DATE FEB 27 1978

Date 6-7-78 Western District Alameda F. Receipt 183478
Operator Westall + Maskey
Lease Hinkle Federal B Well No. 10
Field Shugart Location 27-18-31
County Eddy State New Mexico
Stage Number 1 This Zone ☒ This Well ☐

OG ☐ NG ☐ NO ☒ OO ☐ WD ☐ IW ☐ Misc. ☐ Depth TD/PB 3621 Formation Queen + 4 Rivers
Size Tubing _____ Tubing Perf. _____ Type Packer _____ Set At _____
2 Wt. 9.5 Set From 0 To 3621 Size Liner _____ Wt. _____
To _____ Open Hole: Size _____ From _____ To _____
Size .44 Holes Per Foot 2 Intervals 3354-70, 3420, 3438, 3452, 3490-3506

Tubing Cap.
 Casing Cap. **57**
 Annular Cap.
 Open Hole Cap.
 Fluid to Load
 Pad Volume **120**
 Treating Fluid **780**
 Flush **57**
 Overflush **3**
 Total to Recover **1017**

Time AM/PM	Treating Pressure-Psi		Barrels Fluid Pumped	Inj. Rate BPM	REMARKS
	Tubing	Casing			
12:28	800	open	0	3	Safety meeting - test lines
12:28	1100	}	3	3	Break Circulation
12:41	950		21	3	start mud
					shutdown Acid on spot Pull Tbg.
2:47+		0	0	30	Start pad
2:51		2300	60	30	Start 1/2 ppq 20/40
2:52		2300	84	30	Start 1 ppq 20/40
2:52+		2300	108	30	Start 1 1/2 ppq 20/40
2:53		2300	117	30	1/2 ppq 20/40 on form
2:54		2300	141	30	1 ppq 20/40 on form
2:55		2300	155	30	1 1/2 ppq 20/40 on form
2:59		2300	300	30	Cut sand start pad Run 10 Balls
3:00		2400	357	30	Balls on form
3:01		2500	360	30	St 1/2 ppq 20/40
3:02		2500	384	30	Start 1 ppq 20/40
3:03		2500	408	30	Start 1 1/2
3:03+		2550	417	30	1 1/2 ppq 20/40 on form
3:04		2550	441	30	1 ppq 20/40 on form
3:05		2550	465	30	1 1/2 ppq 20/40 on form
3:10		2450	600	30	Cut sand start Pad Run 10 Balls
3:12		2500	657	30	Balls on form
3:12+		2700	660	30	St 1/2 ppq 20/40
3:13		2700	684	30	St 1 ppq 20/40

Customer Representative Mr. Westall
Western Representative Teddy Gandy
Distribution _____

Job Number

OFFICE OF THE
DIRECTOR OF THE
BUREAU OF THE
CENSUS



1944

1944