

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Aramco, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

JUN 8 '90

WELL API NO.
30-015-22366

1. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
Chevron U.S.A. Inc. /

3. Address of Operator
P.O. Box 670, Hobbs, NM 88240

4. Well Location

Unit Lease 0 : 1980 Feet From The East Line and 660 Feet From The South Line

Section 36 Township 19S Range 27E NM PM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3498' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER: ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

IT IS PROPOSED TO P & A THE SUBJECT WELL AS FOLLOWS:
NOTIFY OCD 24 HRS PRIOR TO START OF P&A OPERATIONS @ 505-748-1283, TOH RECOVER 2 3/8"
PROD TBG & PKR, SET CIBP @ 10100' & CAP W/ 35' CMT, SET CIBP @ 9450' & CAP W/ 35' CMT,
SET 200' BALANCED CMT PLUG F 9212 TO 9012 W/25 SXS, SET 200' BALANCED CMT PLUG 8634 TO
8434 W/30 SXS, CUT 5 1/2" CSG @ 8100'±, SET 200' BALANCED CMT PLUG 50' INSIDE W/ 5 1/2"
STUB 150' ABOVE WOC TAG TO VERIFY PLUG PLACEMENT, SET 200' BALANCED CMT PLUG 5944 TO
5744 W/30 SXS, SET 200' BALANCED CMT PLUG 3050 TO 2850 W/ 30 SXS, SET 200' BALANCED
CMT PLUG 1580 TO 1380 W/ 30 SXS, SET 200' BALANCED CMT PLUG 482 TO 282 W/ 30 SXS,
SET 200' BALANCED CMT PLUG 60 TO SURFACE W/ 10 SXS, CUT OFF WELLHEAD 5' BELOW GL
INSTALL DRY HOLE MARKER, CHANGE WELL STATUS TO PLUGGED & ABANDONED.

* P&A MUD TO BE PLACED BETWEEN ALL PLUGS.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M. E. Akins TITLE Staff Drlg. Engr. DATE 6-7-90

TYPE OR PRINT NAME M. E. Akins TELEPHONE NO. 393-4121

(This space for State Use)

APPROVED BY Johnny Robinson TITLE CUL. INSPECTOR DATE 6-11-90

CONDITIONS OF APPROVAL, IF ANY: