

SWAB REPORT

<u>Run No.</u>	<u>Time</u>	<u>Top of Fluid</u>	<u>Depth Swab From</u>	<u>Rec (bbls)</u>	<u>Remarks</u>
1	10:00 AM	surface	2000	2	
2	10:30 AM	800	2800	2	
3	10:45 AM	1400	3400	1	water
4	10:05 AM	2000	4000	2	
5	11:20 AM	2500	4500	1.8	
6	11:35 AM	3600	5600	2	
7	11:50 AM	4200	6200	0	
8	12:17 PM	4200	6200	1.8	
9	12:40 PM	4300	6300	2	some gas
10	12:56 PM	4500	6500	2	
11	1:20 PM	4600	6600	2	
12	1:32 PM	4600	7100	2	
13	1:45 PM	5000	7500	1.5	
14	2:20 PM	5000	7500	2	
15	2:32 PM	5900	8400	3	
16	2:50 PM	6400	8900	2	good gas blow
17	3:15 PM	6400	8900	3	after run
18	3:35 PM	6300	8800	3	
19	3:50 PM	6400	8900	3	
20	4:15 PM	6400	8900	1	Heads of fluid
21	4:40 PM	7000	9500	1	gas cut. New
22	4:53 PM	7800	SN	2	cups every run.
23	5:12 PM	7600	SN	1	Gas blow during
24	5:26 PM	8500	SN	0	and after run.
25	5:50 PM	8500	SN	1	

RECEIVED

MAY 29 1990

OCD
HOBBS OFFICE