N :, OF COPIES RECEIVED	مــــــــــــــــــــــــــــــــــــــ	ا_ک		:	Form C-103	•		
DISTRIBUTION					Supersedes C 100 == 1 C			
SANTA FE			NEW MEXICO OIL CONSERVATION COMMISSION		C-102 and C Effective 1-			
FILE	17	1						
U.S.G.S.			RECEIVE	, D 5a.	Indicate Ty	ce of Lease		
LAND OFFICE					State X	Fee	• 🔲	
OPERATOR	1		JUN 1 2 1978	5. 8	tate Oil & C	as Lease No.		
	·		JUN % % 1370	' 1	L-4222			
	SU	NDR	NOTICES AND REPORTS ON WELLS		TITTI	HHHH	7777.	
(DO NOT USE THIS FOUSE	RAFF	H PHO	NOTICES AND REPORTS ON WELLS OBALS TO DRILL OR TO EEPEN OR PLUG BACK TO A DIFFERENT RESERVE. N FOR PERMIT - " FORM C-1011 FOR SUCH PROPOSALS."				////	
١.		,	ARTESIA, OFFICI	7. U	Init Agreeme	ent Name		
OIL GAS WELL	X	ļ	OTHER-					
2. Name of Operator				9. F	arm of Leas	se Name		
GULF OIL CORPO	RAT	ION	/	E	ddy "G	Z" State (Com	
. Address of Cherator					ell No.			
P. O. Box 670,	\mathbf{H}^{ϵ}	obbs	, New Mexico 88240	1	Ĺ			
4. Location of Well						10. Field and Pool, or Wildcat		
INNIT LETTER I		1	980 FEET FROM THE South LINE AND 660 FEET	TROW U	Indes. 1	forrow		
				11	TITTI.		TIII,	
East .		e c & * * * *	12 TOWNSHIP 19-S RANGE 27-E	())			1111:	
THE	.INE,	* C 11C	TOTASAIF RANGE		//////		1111.	
	111	III	15, Elevation (Show whether DF, RT, GR, etc.)	12.	County	11111	1111	
	///	////	3521' GL	E	ddy			
16.	Cha	مدد	ppropriate Box To Indicate Nature of Notice, Report o	r Other F	lata			
NOTIC				UENT RE		-		
NOTA		,, ,,,	305520	OLIVI IVE	· OK · Or	•		
PERFORM REMEDIAL WORK	7		PLUG AND ABANDON REMEDIAL WORK	7	A1.74	RING CASING	Γ	
TEMPORARILY ABANDON	า์		COMMENCE DRILLING OPNS.	าี		AND ABANDONME	H	
PULL OR ALTER CASING	า์		CHANGE PLANS CASING TEST AND CEMENT JOB X	สี		AND ABANDORME	*· L_	
			OTHER	7.1				
OTHER								
	mplet	ed Op	rations (Clearly state all pertinent details, and give pertinent dates, inc	luding estim	ated date o	f starting any pr	oposed	
work) SEE RULE 1103.								
hole (474') @ 7 csg. Set @ 474 with 475 sx of WOC 20-1/2 hrs.	7:30 4'. Cla	O AM Ce ass Test	y spudded a 17-1/2" hole @ 10:00 AM, 6-5-78. , 6-6-78. Ran 11 jts & 1 cut jt (446.90') of ment with 200 sx Howco thickset with 1/4# F1 c'" cmt with 1/4# F1ocele & 2% CaCl ₂ . Plug ed casing (13-3/8") to 500# for 30 minutes, -1/4" hole @ 12:30 PM, 6-7-78.	of 13-3/ locele & down @	'8" H-40 2% CaC 1:30 PM	48 # ST&C	: ed	
18. I hereby certify that the i	0	1	above is true and complete to the best of my knowledge and belief.					
SIGNED // ·	Ju!	ومد	Area Engineer		DATE6	-8-78		
15 G	7	A	esset un supervisor, district ii		J'	UN 1 3 1978	}	