

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-4222	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Gulf Oil Corporation		8. Farm or Lease Name Eddy "GZ" State Com
3. Address of Operator P. O. Box 670, Hobbs, NM 88240		9. Well No. 1
4. Location of Well UNIT LETTER <u>I</u> , 1980 FEET FROM THE <u>South</u> LINE AND <u>650</u> FEET <u>1981</u> THE <u>East</u> LINE, SECTION <u>12</u> TOWNSHIP <u>19S</u> RANGE <u>27E</u> C. D. <u>1981</u>		10. Field and Pool, or Wildcat <u>Angel Ranch at Morrow</u>
15. Elevation (Show whether DF, RT, GR, etc.) 3521' GL		12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER _____		OTHER <u>Abandon Morrow sands, recompleting</u> <input checked="" type="checkbox"/> Upper Morrow	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH with tubing and packer. Set CIBP at 10,530'. Perf 10,322-25' with (2) 1/2" JHPF; 10,346-54', 10,382-98', 10-458-64' with (1) 1/2" JHPF (40 holes). Spot acid 10,465'-10,300'. Set packer at 10,265'. Test annulus 750#. Put acid away. Max pres 1600# at 2 BPM, ISIP 1600#. Complete after abandoning Morrow sands and recompleting in Upper Morrow 11-30-81.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED RD Prite TITLE Area Engineer DATE 12-1-81

APPROVED BY W.A. Gressett TITLE SUPERVISOR, DISTRICT II DATE DEC 11 1981

CONDITIONS OF APPROVAL, IF ANY: