

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87504

Form C-103
Revised 10-1-7

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	☒
FILE	☒
U.S.G.S.	
LAND OFFICE	
OPERATOR	☒

APR 26 '88

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
L-4222

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT STRATIGRAPHIC UNIT. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER-

2. Name of Operator
Steve Sell

3. Address of Operator
P. O. Box 5061, Midland, TX 79704

4. Location of Well
UNIT LETTER I 1980 FEET FROM THE South LINE AND 660 FEET FROM East THE LINE, SECTION 12 TOWNSHIP 19S RANGE 27E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
3521' Grd.

7. Unit Agreement Name

8. Name of Lease Name
Eddy GZ State Com.

9. Well No.
1

10. Field and Pool or Wildcat
Angell Ranch
Atoka Morrow

12. County
Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDON ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Existing Casing: 474' of 13 3/8" surface circulated with 675 sxs. 2500' of 8 5/8" intermediate circulated with 1000 sxs. 10914' of 5 1/2" production string cemented with 600 sxs. Top of cement at 8580'.

Existing Perforations: 10322'-10464'.

Proposed Plugging Procedure: Set CIBP at 10272'. Circulate hole with 10# salt gel with 25#/bbl. gel. Spot 60' of cement on top of CIBP. Spot 100' plug from 8700-8600'. Cut off 5 1/2" casing at approximately 8300'. Pull 5 1/2" casing. Spot 130' plug at 8350-8220'. Spot 100' plug at 6670-6570'. Spot 100' plug 4875-4775'. Spot 100' plug 3430-3330'. Set 8 5/8" cement retainer at 2480'. Squeeze shoe, string out of retainer and spot 50' plug on top of retainer. Spot 100' plug & sxs -

Flugging

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Bucky Olson TITLE Agent DATE 4-22-88

APPROVED BY M. Williams TITLE OIL AND GAS INSPECTOR DATE APR 29 1988

CONDITIONS OF APPROVAL, IF ANY: