

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

RECEIVED

Form C-103
Revised 10-1-73

MAR 25 '88

See.

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	
5. State Oil & Gas Lease No.	NM 7794

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- ARTESIA, OFFICE	7. Unit Agreement Name GARDNER DRAW UNIT
2. Name of Operator TOTAL MINATOME CORPORATION ✓	8. Farm or Lease Name GARDNER DRAW UT.
3. Address of Operator 500 DALLAS, SUITE 400, HOUSTON, TX 77002	9. Well No. 3
4. Location of well UNIT LETTER <u>L</u> <u>2100</u> FEET FROM THE <u>SOUTH</u> LINE AND <u>660</u> FEET FROM THE <u>WEST</u> LINE, SECTION <u>17</u> TOWNSHIP <u>19S</u> RANGE <u>21E</u> T19S.	10. Proposed Pool <u>GARDNER DRAW</u> <u>MORROW</u>
11. Elevation (Show whether DF, RT, GR, etc.) 4459 GR	12. County EDDY

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPER. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

ESTIMATED TO BEGIN 4/15/88.

LOAD HOLE WITH 9.5 PPG MUD TO KILL WELL. POOH W/GUIBERSON UNI-PACKER VI AND 2 3/8" TBG. RBIH W/TBG AND SPOT 30 SACK CLASS "H" CEMENT PLUG W/ADDITIVES FROM 6949 - 7236'. PERFORATIONS ARE AT 6999-7104' & 7162-86'. POOH W/TBG. RIH W/CSG CUTTER AND CUT CSG AT 4000' (ESTIMATED) POOH W/RECOVERED 4 1/2" CSG. SPOT 20 SACK CLASS "H" CEMENT PLUG W/ADDITIVES FROM 4050-3950'. SPOT 36 SACK CLASS "H" CEMENT PLUG W/ADDITIVES ACROSS SURFACE CASING SHOE @1743' FROM 1793-1693'. SPOT 5 SACK CLASS "H" CEMENT PLUG W/ADDITIVES AT 10' TO SURFACE. MARK WELL W/A 4" DIAMETER STEEL MARKER SET IN CONCRETE EXTENDING TO 4' ABOVE MEAN GROUND LEVEL. THE MARKER SHALL READ GARDNER DRAW UNIT, WELL NO. 3, SECTION 17, T19S, R21E, EDDY COUNTY, NEW MEXICO.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Pamela Grantham TITLE REGULATORY ADMINISTRATOR DATE 3/21/88

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: