

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instruct  
verse side)

Budget Bureau No. 1004-113  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM 7794

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

GARDNER DRAW UNIT

8. FARM OR LEASE NAME

GARDNER DRAW UT.

9. WELL NO.

3

10. FIELD AND, POOL, OR WILDCAT  
GARDNER DRAW  
MORROW

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

SEC 17, T19S, R21E

12. COUNTY OR PARISH

EDDY

13. STATE

NEW MEXICO

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

TOTAL MINATOME CORPORATION

APR 19 '88

3. ADDRESS OF OPERATOR

500 DALLAS SUITE 400, HOUSTON, TX 77002

O. C. D.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)  
At surface

UNIT L, 2100' FSL, 660' FWL, SEC. 17, T19S R21E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4459 GR

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐

PULL OR ALTER CASING

☒

FRACTURE TREAT

☐

MULTIPLE COMPLETE

☐

SHOOT OR ACIDIZE

☐

ABANDON\*

☒

REPAIR WELL

☐

CHANGE PLANS

☐

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐

REPAIRING WELL

☐

FRACTURE TREATMENT

☐

ALTERING CASING

☐

SHOOTING OR ACIDIZING

☐

ABANDONMENT\*

☐

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

CURRENT PERFORATIONS ARE AT 6999 - 7186'. LOAD HOLE WITH 9.5 PPG MUD TO KILL WELL. POOH W/GUIBERSON UNI-PACKER VI AND 2 3/8" TBG. RBIH W/CIBP AND SET AT 6975'. SPOT 35 SACKS CLASS 'H' CEMENT W/ADDITIVES ON CIBP. LOAD HOLE W/9.5 PPG MUD TO SURFACE.

ATTEMPT TO SALVAGE 4 1/2" PRODUCTION CSG. CUT 4 1/2" CSG. AT 6000' AND POOH. SPOT 35 SACKS CLASS 'H' CEMENT AT 6050'. TAG TOP OF CEMENT. SPOT 25 SACKS CLASS 'H' CEMENT AT THE FOLLOWING DEPTHS: 5610', 4300' AND 3350'. SPOT 35 SACKS CLASS 'H' CEMENT AT 1760'. TAG TOP OF CEMENT. SPOT 35 SACKS CLASS 'H' CEMENT AT 510'.

SPOT 5 SACKS CLASS 'H' CEMENT AT 50' TO SURFACE. MARK WELL WITH A 4" DIAMETER STEEL MARKER SET IN CONCRETE EXTENDING 4' ABOVE MEAN GROUND LEVEL. THE MARKER SHALL READ: GARDNER DRAW UNIT, WELL NO. 3, SEC. 17, T19S, R21E, EDDY COUNTY, NEW MEXICO.

THE WELL IS BEING ABANDONED AS IT IS NO LONGER ECONOMICAL TO PRODUCE.

RECEIVED  
APR 5 11 03 AM '88  
CITIZENSHIP  
AREA

RECEIVED

18. I hereby certify that the foregoing is true and correct

SIGNED

*Danella Hawthorn*

TITLE

REGULATORY ADMINISTRATOR

DATE

4/4/88

(This space for Federal or State office use)

CHIEF, MINERAL RESOURCES

APPROVED BY

TITLE

DATE

4-18-88

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side