## NMOCC COPY

## UNITED STATES DEPARTMENT OF THE INTERIOR

	Budg	et Bure	au N	ło. 42–F	R1424
5. LEASE					
NM	779	4		-	
6. IF INDIAN, ALL	OTTEE	OR T	RIBI	E NAM	E
7. UNIT AGREEM	ENT N	AME			
Gardner Draw	Ūni	t .			
8. FARM OR LEAS					
έ.		÷		77 :	
9. WELL NO.					
4 월		<u> </u>		: - :	
10. FIELD OR WILD	CAT N	AME		·	
Wildcat			1999	2 3 X	<b>.</b>
11. SEC., T., R., M.	OR B	LK. A	ND !	SURVE	Y OR
AREA -	-	ر		-	
Sec. 18, T-1	9-S.	R-2	1-1	3	
12. COUNTY OR PA	RISH	13.			
Eddy	_ 1	New	Me	exico	)
14. API NO.		-	:		
			•	-	
15. ELEVATIONS (	SHOW	DF, I	KDB	, AND	WD)
4500 <u>'</u> G	L		-		
ř				•	
#15	ž.,	· -	-		
	٠.,	-			
(NOTE: Report result	sofmu	Itiple o	omo	letion o	700e
change on Fo	orm 9–3	30.)		- :	20.16
	-	-	- <u>-                                  </u>	_	*-
÷		<u>:</u>	ا ن	1.	٠.
		Ξ	_	1.	-
·		•			

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plus back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME Gardner Draw Unit			
	8. FARM OR LEASE NAME			
1. oil gas well other representation	9. WELL NO.			
2. NAME OF OPERATOR	4 8 E 9 E 2 E 1			
Phoenix Resources Company	10. FIELD OR WILDCAT NAME			
3. ADDRESS OF OPERATOR SUITE 290ARTESIA, DEPICE	Wildest Find Werker			
Une Marienfeld Place, Midland, Texas 79701	11. SEC., T., R., M., OR BLK. AND SURVEY O			
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  Unit "J"	AREA			
AT SURFACE: 1980' FSL,2200' FEL,Sec 18,T19,R21	Sec. 18, T-19-S, R-21-E  12. COUNTY OR PARISH 13. STATE			
AT TOP PROD. INTERVAL: Same	Eddy New Mexico			
AT TOTAL DEPTH: Same	14. API NO.			
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA				
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WE			
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	45001 GL			
TEST WATER SHUT-OFF				
FRACTURE TREAT				
SHOOT OR ACIDIZE  REPAIR WELL				
PULL OR ALTER CASING	(NOTE: Report results of multiple completion or zor change on Form 9-330.)			
MULTIPLE COMPLETE				
CHANGE ZONES				
ABANDON*				
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di	all pertinent detalls, and give pertinent date:			
including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinent				
1-7-79 Ran Drill Collars in hole, lay down sa				
Ran drill pipe in hole to plug and aba				
• • • • • • • • • • • • • • • • • • • •	O Sacks A Paragraph I have a			
	Sacks RECEIVED			
· · ·				
	O Sacks JAN 2 3 1979			
Plug #5 3275'-3375' (100') 30 Plug #6 1735'-1835' (100') 30	O Sacks			
Plug #7 10 sacks at surface	U.S. GEULÜGIERL SERVE			
Tug ", To suchs de surruco	ARTESIA NEW MEXICO			
1-8-79 Remove BOP - clean pits - release rig	@ 6:00 P.M.			
Verbal approval from USGS, Artesia, fo				
**				
Subsurface Safety Valve: Manu. and Type	Set @			
18. I hereby certify that the foregoing is true and correct				
SIGNED OFFICENCE TITLE Agent	DATE1-16-79			
/ (This space for Federal or State office	e use)			
ACTING DISTRICT ENG	INEER TO TO TO TO THE TOTAL TOT			
APPROVED BY ST. XI ZOUL TITLE CONDITIONS OF APPROVAL, IF ANY:	DATE			
J				