

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

RECEIVED

JUN 11 1992

WELL API NO.
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name North Lake McMillan
8. Well No. 1
9. Pool name or Wildcat Wildcat San Andres

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER Plugged & Abandon

2. Name of Operator
Robert N. Enfield

3. Address of Operator
P. O. Box 2431, Santa Fe, NM 87504-2431

4. Well Location
Unit Letter J : 1980 Feet From The South Line and 1980 Feet From The East Line
Section 12 Township 19 South Range 26 East NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3289.GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4/28/92

Ran & set 9-5/8" CIBP at 1450'. Go in hole open ended to 1441', circulate hole w/gelled 10% brine. Pumped 180 barrels total, break circulation at 138 barrels. Mix & pump 15 sacks. Pull out of hole to 375'. Mix & pump 40 sacks cement. Pull up hole to 60'; mix & pump 20 sacks cement to surface. (cement: Premium Plus Neat, 14.8#/gallon). Set dry hole marker, clean up location. Mike Stubbelfield with MNOCN on location and witnessed plugs

Post ID-2
6-19-92
PxA

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Robert N. Enfield TITLE Operator DATE 6/9/92

TYPE OR PRINT NAME Robert N. Enfield

TELEPHONE NO. 505-988-2863

(This space for State Use)

APPROVED BY Mike Stubbelfield TITLE OIL AND GAS INSPECTOR DATE JUL 28 1992

CONDITIONS OF APPROVAL, IF ANY: