Capy to SF N TO C G GOPT Form approved. Budget Bureau No. 42-R1424. SUBMIT IN TRIPLICATE* UNITED STATES Form 9-331 DEPARTMENT OF THE INTERIOR verse side) (May 1963) 5. LEASE DESIGNATION AND SERIAL NO. GEOLOGICAL SURVEY NM-0554950-A 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT_" for such proposal E 7. UNIT AGREEMENT NAME 1. OIL WELL GAS WELL X \Box DRY HOLE OTHER FB 2 2 1979 8. FARM OR LEASE NAME 2. NAME OF OPERATOR Jones Federal (NCT-B) GULF OIL CORPORATION **D**. **G**. **C**. 9. WELL NO. P. O. Box 670, Hobbs, New Mexico 88240 LI. L. ARTESIA LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface ADDRESS OF OPERATOR 3. ARTESIA, OFFICE 2 10. FIELD AND FOOL, OR WILDCAT Cemetary Morrow 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 33, T-20-S, R-25-E 1980' FSL & 1980' FWL 12. COUNTY OR PARISH | 13. STATE 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14. PERMIT NO. 3642.6' GL Eddy New Mexico Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data 16. SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO : REPAIRING WELL WATER SHUT-OFF TEST WATER SHUT-OFF PULL OR ALTER CASING FRACTURE TREATMENT ALTERING CASING MULTIPLE COMPLETE FRACTURE TREAT ABANDONMENT* XX SHOOTING OR ACIDIZING ABANDON* SHOOT OR ACIDIZE (Other) CHANGE PLANS REPAIR WELL (NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* (Other) Pursuant to verbal approval by Joe Lara: 10,020' TD. Spot 75 sacks of Class "C" Neat cement from 9320 - 9520' (top of Morrow). Spot 75 sacks of Class "C" Neat cement from 8350 - 8550' (top of Strawn). Spot 50 sacks of Class "C" Neat cement from 6450 - 6600' (top of Wolfcamp). Spot 50 sacks of Class "C" Neat cement from 4450 - 4600' (Bone Spring). Spot 75 sacks of Class "C" Neat cement from 2450 - 2650' across 8-5/8" casing set @ 2550'. Spot 35 - 50 sacks of cement surface plug. Remove wellhead. Install dry hole marker. Clear & clean location. 18. I hereby certify that the foregoing is true and correct 01-26-79 Area Engineer DATE TITLE SIGNED (This space for Federal TITLE ACTING DISTRICT ENGINEER FEB 21 1979 DATE __ CONDITIONS OF APPROVAL, IF ANY :

*See Instructions on Reverse Side