

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

NOV 12 1980

Form C-103
Revised 10-1-79

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	/
LAND OFFICE	/
OPERATOR	/

O. C. D.
ARTESIA, OFFICE

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.
L-621

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Gulf Oil Corporation ✓	8. Farm or Lease Name Eddy "GM" State
3. Address of Operator P. O. Box 670, Hobbs, NM 88240	9. Well No. 2
4. Location of Well UNIT LETTER <u>G</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>2180</u> FEET FROM THE <u>East</u> LINE, SECTION <u>36</u> TOWNSHIP <u>19S</u> RANGE <u>27E</u> COUNTY <u>MEMPHIS</u>	10. Field and Pool, or Wildcat Wildcat Bone Springs
15. Elevation (Show whether DF, RT, GR, etc.) 3438' GL	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH with production equipment. Set CIBP at 5100', circulate hole with abandonment mud. Spot 10 sacks cement, plug at 5100' to cap CIBP. Spot 40 sacks cement 4830'-4730'. Spot 100' cement plug 3050'-2950'. Tagged plug at 2928'. Spotted 35 sacks cement at 450' & 15 sacks at 50'. Install dry hole marker. Cleaned and cleared location. P&A complete 11-4-80.

POST ID-2
P-1
11-11

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED RDPite TITLE Area Engineer DATE 11-10-80

PROVED BY Mike Stuffed TITLE OIL AND GAS INSPECTOR DATE JAN 05 1981

CONDITIONS OF APPROVAL, IF ANY: