

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

|                        |                                     |
|------------------------|-------------------------------------|
| NO. OF COPIES RECEIVED |                                     |
| DISTRIBUTION           |                                     |
| SANTA FE               | <input checked="" type="checkbox"/> |
| FILE                   | <input checked="" type="checkbox"/> |
| U.S.O.S.               |                                     |
| LAND OFFICE            |                                     |
| OPERATOR               | <input checked="" type="checkbox"/> |

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-73

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

|  |  |   |
|--|--|---|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <span style="float: right;">AUG 24 '88</span>   |  | 7. Unit Agreement Name                                  |
| 2. Name of Operator<br>RALPH NIX OIL, INC.   |  | 8. Farm or Lease Name<br>Hondo Barbara                  |
| 3. Address of Operator<br>P. O. Box 440, Artesia, New Mexico 88210   |  | 9. Well No.<br>1  |
| 4. Location of Well<br>UNIT LETTER <u>J</u> 1980 FEET FROM THE <u>South</u> LINE AND 1980 FEET FROM<br>THE <u>East</u> LINE, SECTION <u>11</u> TOWNSHIP <u>19S</u> RANGE <u>26E</u> N.M.P.M. |  | 10. Field and Pool, or Wildcat<br>Four Mile Draw Morrow |
| 15. Elevation (Show whether DF, RT, CR, etc.)<br>3303' GL  |  | 12. County<br>Eddy                                      |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐  
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐  
ALTERING CASING ☐  
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/27/88 RU Baber Service. Install BOP. Could not unset packer. Tbg pulled off from packer. POOH w/147 stands of 2 3/8" tbg & 2 10' subs. SDON.

7/28/88 RUWL. RIH & tag packer at 9355'. Pull up & set CIBP at 9330'. RIH w/tbg, 146 stands & 1 sgl. Circ hole w/mud, spot 10 sx on top CIBP. Stretched csg, free point calculated at 5970'. SDON.

7/29/88 Install BOP. RIH to 7550', spot 25 sx cement. POOH to 7025', spot 25 sx cement. POOH to 6699', spot 25 sx cement. SDON.

8/01/88 RIH to 5809', shot csg off. Lay down 177 jts 4 1/2" csg. RIH w/tbg to 5869', spot 50 sx cement. SDON.

8/02/88 RIH & tag plug at 5620'. POOH to 3950', spot 25 sx cement. POOH to 3150', spot 25 sx cement. POOH to 1651', spot 50 sx cement. in & out of 8 5/8" csg shoe. WOC. RUWL. RIH, unable to tag plug. RIH w/tbg, spot 25 sx at 1600'. POOH & SDON.

8/03/88 RIH & tag plug at 1540'. POOH to 400', spot 35 sx cement. Cut wellhead off and anchors. Spot 10 sx surface plug, install dry hole marker.

8/17/88 Fill in pit. Clean location. P&A complete. Ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ralph Nix TITLE President DATE 8/23/88

APPROVED BY Daniel Moore TITLE Geologist DATE 10/6/88

CONDITIONS OF APPROVAL, IF ANY:

Post #0-1  
9-2-88  
P&A