Operator SDX Resources Inc	TOPS TOPS
Well State 32 Com #1	T. Salt 3 co
Unit B Section 32 Township 19 Range 2	<u> </u>
API# 30-0/5 Z2826	Yates
	Glorieta
	Delaware
	Bone Sp. 4450
	Abo
	Wolfcamp 8649
	Morrow
	Devonian
	Fusselman
	Other
	• Contact OCD 24 hrs. prior to any work done.
	• Salt gel mud consisting of 10# brine with 25#
	of gel per barrel must be placed between each
	plug
	• Install dry hole marker as per rule 202.B.2
	Plugs are to be set from point indicated up
1/3/4	• Plugs must not be less than 100' or 25 Sacks
	of cement, whichever is greater, unless
360'	specifically indicated.
cue	_ •
	• Shoe and stub plugs will be 50' above and
	below shoe or stub and tagged.
	• Surface plug will be from 0'- 60'
	 Where plugs are required cement must be
, , ,	placed inside and outside of all casing
841 / Shoe Plug 2558-2658 - +A9	string(s), in the correct footage or sacks
848 A KShort 17109 2000	required, if no cement exists.
2608. Circ	 Plugs to be tagged will be indicated.
nine .	-
1	
FRITE 5200' Squeeze Cont to Sinface - LTD TOC - (Tanp. Surv.)	ave 100' gent inside pine 5100. 520
Herf@ 5200 Squeeze Chi	-
5210 - 10C - (124) SOIV)	
7120 -> DV Tool ~ 100' Plug 7070' 40 7170 ~ 25 Sx. Plug @ 8649 ~ set CJAPM/ 35' co. + 9400'	
1160 - 100. plug 7070 40 1140	
2 25 Sx. Plug @ 8649	
1 CT 40 m/ 35' Cm + 9400'	
Z-Ser Carr	
516. 9553 - APPS 430 and 9.97	
	•
7570 12	
41/2	
11,135'	
77/8hde	. t