

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 064670

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

State Federal Com. "22"

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

Undesignated (Morrow)
11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 22, T. 19 S., R. 28 E.

12. COUNTY OR PARISH 13. STATE

Eddy

NM

1. OIL ☐ GAS ☒ OTHER ☐
WELL WELL

2. NAME OF OPERATOR

Southland Royalty Company ✓

3. ADDRESS OF OPERATOR

1100 Wall Towers West, Midland, TX 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

1980' FNL & 990' FWL, Sec. 22, T. 19 S., R. 28 E.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3411.2' GR

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

1. Blew well down, released PKR. Pull tbg. to 7000'.
2. POH w/tbg.
3. Ran CIBP & set @ 8000'. Dump 35' cmt. on top of plug. RMVD WH.
4. Shot 4-1/2" csg. off @ 7015'. LD 200 jts.
5. Ran 2-3/8" tbg. to 7110'. Spotted 65 sxs. 7110-6815'. Pulled tbg. to 4800'.
6. Tagged plug @ 6750'. Spotted 60 sx. from 5160 - 4951'. Pulled tbg. to 2550'.
Spotted 50 sx. from 2550-2432'. Ran tbg. to 450'. Spotted 40 sx. from
450-318'.
7. Spotted 15 sx. from 60' to surface. Cut off WH. Welded on plate. Installed
dry hole marker. P&A compl. 1-20-82.

This procedure approved by Peter Chester USGS Roswell, NM 12-8-81.

RECEIVED
JAN 25 1982

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

(This space for Federal or State office use)

APPROVED BY: (Off. Seal) PETER CHESTER

CONDITIONS OF APPROVAL: NOV 2 1982

FOR

JAMES A. GILLHAM
DISTRICT SUPERVISOR

TITLE Dist. Prod. Mgr.

DATE 1-21-82

TITLE

DATE

*See Instructions on Reverse Side