


[illegible]

"Existing Condition"



"After condition"
dry hole marker removed
surface plug drilled out
319-450 plug drilled out
2432-2550 plug drilled out
to 2450.
Nothing below 2450-
will be disturbed.
Complete as necessary
between 1800-2200-
w/ perforation thru
the 8 5/8" csg.

REVISÉ: