

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO.
30-015-22941

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
L-4397-3

7. Lease Name or Unit Agreement Name:
Merchant State

8. Well No.
1

9. Pool name or Wildcat
Palmillo (Bone Springs)

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
3384.4' GL; 3403' KB

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
Bass Enterprises Production Co.

3. Address of Operator
P.O. Box 2760 Midland, TX 79702-2760

4. Well Location
Unit Letter H : 1980' feet from the North line and 660' feet from the East line
Section 1 Township 19S Range 28E NMPM County Eddy

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
3384.4' GL; 3403' KB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: Return to Production <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Move pumping unit and set.
Hook up electrical power, open flowline, turn well on and check pump action.
MIRU Key Well Service, shop pump for repairs. Test 2-3/8" tubing, replace two joints of 2-3/8" tubing. Space out well, load tubing with produced water.
Pressure test tubing to 500 psi, held ok. RDMO PU

Return well to production.

2/28/02 9 BO + 50 BW + 228 MCF

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tami Wilber TITLE Production Clerk DATE 3/6/02

Type or print name Tami Wilber Telephone No. 915-683-2277

(This space for State use)

APPROVED BY [Signature] TITLE Field Rep DATE MAR 12 2002

Conditions of approval, if any: