

State of New Mexico
Energy Minerals and Natural Resources Departmentc/sf
Oper.Submit 3 Copies
to Appropriate
District OfficeDISTRICT I
P.O. Box 1980, Hobbs, NM 88240DISTRICT II
P.O. Drawer DD, Artesia, NM 88210DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

OCT 20 1993

WELL API NO.

30-015-22953

5. Indicate Type of Lease

STATE ☒FEE ☐

6. State Oil & Gas Lease No.

L-5033

7. Lease Name or Unit Agreement Name

Amoco State HE

8. Well No.

1

9. Pool name or Wildcat

Artesia Queen-Grayburg-San Andres

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒GAS
WELL ☐

OTHER

2. Name of Operator

YATES PETROLEUM CORPORATION

3. Address of Operator

105 South Fourth Street - Artesia, NM 88210

4. Well Location

Unit Letter K : 1980 Feet From The South Line and 1980 Feet From The West LineSection 11Township 19SRange 27E

NMPM

Eddy

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3482' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐PLUG AND ABANDON ☒TEMPORARILY ABANDON ☐CHANGE PLANS ☐PULL OR ALTER CASING ☐OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐PLUG AND ABANDONMENT ☐CASING TEST AND CEMENT JOB ☐OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon well as follows:

1. Pull rods, pump and tubing.
2. Run 2-3/8" tubing to PBTD: 2890'.
3. Load hole with 10#/gallon brine containing 25#/barrel salt gel.
4. Set a 25 sack Class "C" 2% CaCl₂ plug from 1702-1552' (across perforations).
5. Pull tubing to 1300' and circulate hole clean.
6. WOC 4 hours and tag plug.
7. Set a 25 sack Class "C" plug from 564-414' (across 13-3/8" shoe).
8. Set a 25 sack Class "C" plug from 150' to surface.
9. Install regulation abandonment marker.

NOTE: NOTIFY OCD - ARTESIA (748-1283) 24 HOURS PRIOR TO COMMENCING OPERATIONS.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Rusty Klein

TITLE

Production Clerk

DATE Oct. 19, 1993

TYPE OR PRINT NAME

Rusty Klein

505-748-1471
TELEPHONE NO.

(This space for State I

ORIGINAL SIGNED BY RAY SMITH

OIL AND GAS INSPECTOR

DATE NOV 02 1993

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY: