

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

C/SF

SUNDRY NOTICES AND REPORTS ON WELLS BY

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> PXA	5. LEASE DESIGNATION AND SERIAL NO. LC-029392(a)
2. NAME OF OPERATOR Amoco Production Company	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P.O. Box 68, Hobbs NM 88240	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FSL X 2310' FWL (Unit N, SE/4 SW/4)	8. FARM OR LEASE NAME Greenwood PGU Fed G
14. PERMIT NO.	9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3627.8' GR	10. FIELD AND POOL, OR WILDCAT Und. Bone Springs
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 35-18-31
	12. COUNTY OR PARISH Eddy
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Propose to PXA as follows:

1. POH with thg and pkr. (pkr set at 8006')
2. RIH and set CTBP at 7150' cap with 250' class c' meat (25 ovs)  
\* Place mud between all plugs
3. Spot a 250' plug (25 ovs class c' meat) from 4925' - 4675'
4. Spot a 250' plug (25 ovs class c' meat) from 920' - 670'
5. Spot a 50' surface plug (5 ovs class c' meat)
6. Clean location and erect PXA marker

0 + 6 BLM, Carlsbad 1-JRB 1-FIN 1-GCC

18. I hereby certify that the foregoing is true and correct

SIGNED

*Nancy C. Clark*

TITLE

*Asst. Admin. Analyst*

DATE

*12-20-84*

(This space for Federal or State office use)

APPROVED BY

TITLE

*OFB:SCA*

DATE

*12-28-84*

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side