

RECEIVED BY
APR 18 1985
O. C. D. use this form for proposals to drill or to deepen or plug back to a different reservoir.
ARTESIA, OFFICE

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

1. NAME OF OPERATOR
2. ADDRESS OF OPERATOR
3. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
4. PERMIT NO.
5. ELEVATIONS (Show whether DF, RT, GR, etc.)

5. LEASE DESIGNATION AND SERIAL NO.
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
9. WELL NO.
10. FIELD AND POOL, OR WILDCAT
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
12. COUNTY OR PARISH
13. STATE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRAC TURE TREAT	<input type="checkbox"/>	FRAC TURE TREATMENT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	(Other)	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		
PULL OR ALTER CASING	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	ALTERING CASING	<input checked="" type="checkbox"/>
ABANDON*	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

RIH and set CIBP at 7148' and copped with 25 sxs, loaded hole with 10" brine gel. Pulled tbg to 4903' and spotted 25 sxs cmt. Pulled tbg to 931' and spotted 25 sxs cmt. Spotted a 50' cmt plug at surface. Installed PXA marker.

075 BLM, C 1-JRB 1-FJN 1-GCC

18. I hereby certify that the foregoing is true and correct

SIGNED Harry C. Clark TITLE Asst. Admin. Analyst DATE 1-16-85

(This space for Federal or State office use)

APPROVED BY Don Wood TITLE Adm. DATE 4-15-85

CONDITIONS OF APPROVAL, IF ANY

*See Instructions on Reverse Side

Post #D-2
2-8-85
PXA