

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLI
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

C/SF

SUNDRY NOTICES AND REPORTS RECEIVED BY

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM-14996	
2. NAME OF OPERATOR Cotton Petroleum Corporation		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR 420 Wall Towers West, Midland, Texas 79701		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1880' FSL & 1980' FWL		8. FARM OR LEASE NAME Federal 11	
14. PERMIT NO.		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) RKB 3451'		10. FIELD AND POOL, OR WILDCAT Boyd Morrow	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 11, T-19-S, R-25-E	
		12. COUNTY OR PARISH Eddy	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12-6-81 - 9300' TD; 8950' PBTD. Set CIBP @ 9000'. Cap with 50' cem.
Cut & pulled 5384' 4-1/2" casing. Set 150' cem plug 75'
in and out of 4-1/2" stub @ 5384'. Plug @ 4331-4431'. Set
100' cem plug 2450-2550', 1164-1264'. 50' in and out of
8-5/8" csg. shoe. Set 10 sx plug @ surface. Cut off 8-5/8"
head. Set marker.
WELL PLUGGED AND ABANDONED.

Received approval from George Stewart, USGS, Roswell of
"Notice of Intention to Abandon" on November 19, 1980.

Post ID-2
7-26-85
P+H

APR 16 1981

18. I hereby certify that the foregoing is true and correct

SIGNED Tom Allen TITLE Engineer DATE 4-8-81

(This space for Federal or State office use)

APPROVED BY 0.8.50 TITLE _____ DATE 7-24-85

CONDITIONS OF APPROVAL, IF ANY: