

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.O.S.	
LAND OFFICE	
OPERATOR	1

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
648

SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT DEPTH. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	7. Unit Agreement Name
2. Name of Operator GULF OIL CORPORATION	8. Farm or Lease Name Eddy "AV" State Com
3. Address of Operator P. O. Box 670, Hobbs, NM 88240	9. Well No. 1
4. Location of Well UNIT LETTER L, 1980 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 27 TOWNSHIP 19S RANGE 28E N.M.P.M.	10. Field and Pool, or Wildcat Under Winchester Morrow
15. Elevation (Show whether DF, RT, GR, etc.) 3358' GL	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☒	CASING TEST AND CEMENT JOB ☐	OTHER ☐
OTHER <u>Abandon existing intervals & add new perfs</u>			

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11,300' TD 11,262' PB Kill well w/2% KCL wtr w/3/4 of 1% KW-94 +1 gal RP-2336/1000 gal +10# K-470/150 bbls. Set 5 1/2" CIBP near 11,020'. Test BP to 1000# (do not set in collar). Perf intervals 10,954-59' & 10,970-75' w/(2) 1/2" o-phase decentralized burrless JHPF (20 holes). GIH w/pkr & SN on 2-3/8" tbg; test to 5000#. Spot 7 1/2% HCL acid from 10,970' up to 10,900'. Pull pkr to 10,900' & reverse 2 bbs 2% KCL water to flush excess acid from annulus. Set pkr & put acid away by ppg 5 bbls 2% KCL water. Swb & test well.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED N.B. Sikes Jr. TITLE Area Engineer DATE

APPROVED BY W.A. Gussert TITLE CHIEF ENGINEER, DISTRICT I DATE 11-1-80

CONDITIONS OF APPROVAL, IF ANY: