Submit 3 Copies	State of New Me	exico		// Form C-103	
to Appropriate District Office	Er /, Minerals and Natural Re	sources Departme.	,	Revised 1-1-89	
			(~ 1/1/	
STRICT I OIL CONSERVATION DIVISION		N DIVISION	WELL API NO.	<u> </u>	
P.O. Box 1980, Hobbs, NM 88240	2040 Pacheco St.				
DISTRICT II	Santa Fe, NM 87	505	30-015-		_
P.O. Drawer DD, Artesia, NM 88210	277	12 13 14 15 16 13	sIndicate Type of Lea		_
DISTRICT III	(210)	A S		STATE FEEX	X.
1000 Rio Brazos Rd., Aztec, NM 87410	/ <u>R</u>	T	State Oil & Gas Lea	ise No.	
	/6-	111 1633 13 \			
SUNDRY NOT	ICES AND REPORTS ON WEL	STEINED 2			
DIFFERENT RESER	PPOSALS TO DRILL OR TO DEEPEN RIVOIR. USE "APPLICATION FOR PER	MITARTESIA NO	₁Lease Name or Uni	it Agreement Name	
	-101) FOR SUCH PROPOSALS.)	AS AS			l
Type of Well:	N/a	150			
OIL GAS WELL WELL	OTHER		Parino		
2Name of Operator			₅Well No.		\neg
Nearburg Producing	Company		1		
Address of Operator	2 C. de 120 Wd41a	- d TV 7070'	Pool name or Wildo		N
4Well Location	2, Suite 120, Midla	na, 1x /9/0.	Dagger D	law; opper renn	ᅪ
	O Cosith	tine and 660		Fact	
Unit Letter :198	OFeet From The South	Line and	Feet From The	<u>East</u> Line	
Section 23	Township 19S F	Range 25E	NMPM	Eddy County	
Page 1997	10Elevation (Show whether DF, I	··· · · · · · · · · · · · · · · · · ·	HIVITIVI	244y County	
paragraphs and	3,417'GR				
11 Check A		ture of Notice Do	ant or Other	Doto	
Office Appropriate Box to indicate Nation of Notice, Neport, of Other Bata					
NOTICE OF INTENTION TO: SUBS				EPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING	
		COMMENCE DRILLING O			
TEMPORARILY ABANDON XX	CHANGE PLANS	PNS.	PLUG AND ANBANDONMENT		
PULL OR ALTER CASING		CASING TEST AND CEME	NT JOB		
OTHER.	OTHER:				\Box
OTHER:		OINER:			
12Describe Proposed or Completed Operation	is (Clearly state all pertinent details, and give	pertinent dates, including es	timated date of startin	g any proposed	
work) SEE RULE 1103.					
Nearburg Producing	Company requests ap	proval to ter	mporarily	abandon the wel	1
by the procedure 1		•			
1					
1) POH w/ produ	ction setting.				
2) Set CIBP @ 7,700' w/ 18' cmt on top. New PBTD @ 7,682'					
	CIBP to 500 psi.				
4) RDMO well se	rvice unit.				
	_				
I hereby certify that the information above is	true and complete to the best of my knowled	dge and belief.			
The state of the s	III I Somprose to the book of my knowled	-3			

TYPE OR PRINT NAME

TELEPHONE NO.

TITLE Mgr Dr1g & Prod DATE 12/8/98

TELEPHONE NO.

TITLE FIELD Rep. I DATE Dec. 14-98

CONDITIONS OF APPROVAL, IF ANY: