

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501
JUN 14 1982

Form C-103
Revised 10-1-78

| | |
|------------------------|-------------------------------------|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | <input checked="" type="checkbox"/> |
| FILE | <input checked="" type="checkbox"/> |
| U.S.O.S. | |
| LAND OFFICE | |
| OPERATOR | <input checked="" type="checkbox"/> |

O. C. D.
ARTESIA, OFFICE

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
LG-5096

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|---|---|
| 1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- | 7. Unit Agreement Name |
| 2. Name of Operator Gulf Oil Corporation ✓ | 8. Farm or Lease Name Eddy "IL" State Com |
| 3. Address of Operator P. O. Box 670, Hobbs, NM 88240 | 9. Well No. 1 |
| 4. Location of Well UNIT LETTER E 1980 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 30 TOWNSHIP 19S RANGE 29E NMPM. 10. Field and Pool, or Wildcat Bone Springs | 12. County Eddy |
| 15. Elevation (Show whether DF, RT, GR, etc.) 3323' GL | |

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

| | | | |
|--|---|--|--|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input checked="" type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> | CASING TEST AND CEMENT JOBS <input type="checkbox"/> | |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH with packer and tubing. Set CIBP at 5390'. Circulate hole with abandonment mud. Cap CIBP with 35' cement. Cut casing at 4407'; POH with casing. Set 100' plug 4457'-4357' (50' inside casing & 50' in open hole). Spot cement plug 4100'-4000'. Spot cement plug 3130'-3030'. Spot cement plug 2985'-2885' (50' inside & 50' outside casing shoe). Tag cement at 2885'. Spot 12 sack surface plug. Install dry hole marker. Clean and clear location. P&A 6-3-82.

*Installed well station
for A ID-2
6-25-82*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *R.D. Pitzer* TITLE Area Engineer DATE 6-10-82

APPROVED BY *Samy Brooks* TITLE *Geologist* DATE 6-4-84

CONDITIONS OF APPROVAL, IF ANY: