ETTER EWINERCO			
an the state of the second			
6. of	IL CONSERVA		F
ENSTINES TRON	P. O. BOX	2088	Form C-203 Kevised 10-1-78
JANTAPL 1	SANTA FE, NEW	MEXICO 87501	
+ 1 L L	4		Sa. Indicate Type of Lesso
	3 - NMOCC - Artesia	KEY 2 0 1981	State X Fee
OPERATOR /	1	··· -	5. State Cill & Gas Lease No.
//··	l - J.L. Conquest - Fo	O. C. D.	E-2943
SUNDR	Y NOTICES AND REPORTS ON		
, i	- <u> </u>		7. Unit Agreement Name
	ОТНЕЯ-		
Name of Operator		<u> </u>	8. Farm or Leuse Name
Threshold Development Company			Conoco "10" State Com
3. Address of Operator			9. Well No.
1100 Gihls Tower West, Midland, Texas 79701			1
1. Location of Well			10. Field and Pool, or Wildcat
			Turkey Track Atoka Gas
UNIT LETTER	FEET FROM THE SOUCH	LINE AND VUV FEET FROM	
	10 100	205	
THE EASL LINE, SECTI	DN 10 TOWNSHIP 195	RANGE ZYE NMPM.	
	15. Elevation (Show whether I	DF. RT. GR. etc.)	12. County
	3374.8' 0		Eddy (()))
<u> </u>			<u></u>
	Appropriate Box To Indicate N	-	
NOTICE OF INTENTION TO: SUBSEQUENT			T REPORT OF:
	r		
PERPORM REMEDIAL WORK	PLUG A O ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	L
		OTHER	L_I
OTHER	[_]		

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed wirk) SEE RULE 1103.

By Case No. 7077, Order No. R-6539 the Oil Conservation Division granted approval to complete the Conoco "10" State Com Well No. 1 as a dual completion (conventional) to produce oil from the Wolfcamp formation and gas from the Atoka formation through parallel strings of tubing.

For various reasons, it was decided not to attempt to dually complete this well but to perform only the portion of the workover which called for fracturing the current producing interval, Turkey Track Atoka perforations 10,776' to 10,790' with 5200 gals. gelled water, 15,000# 20/40 sand and 7150 gals. CO₂. This job was performed on May 5, 1981. Prior to workover well was flowing 6.96 BC, 523 MCFGPD, no water, FTP 600#.

- 1) MI&RU Dresser-Titan 5-5-81.
- 2) Fracture treated w/4242 gals. gelled water (XL-4) 8364# 20/40 sand and 5208 gals. CO₂. BDP 9200 psi, Max. rate 10 BPM at 9200 psi, Avg. rate 9 BPM at 9600 psi. Packer failed or 2-3/8" tubing ruptured at this point during job. Pressure increased immediately to 8800 psi on annulus. Shut pump down and released pressure. Continued on page 2

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief,

ALLES Peggya, Redman	Ingineer Assistant	DATE May 18, 1981
APPROVED BY W. G. Gressett	TITLE SUPERVISOR, DISTRICT, M	DATE MAY 2 6 1981