THRESHOLD DEVELOPMENT COMPANY Conoco 10 State #1 Section 10-T19S-R29E Eddy County, New Mexico

APPLICATION FOR PERMIT TO DRILL, RE-ENTER, DEEPEN, PLUGBACK CONTINUED:

- 4. Perforate 9130-9170', acidize as necessary for production.
- 5. Swab test/pump test.
- 6. Place well into production.

If decision is made to add more perforations, will be as follows:

- 7. Pump 2% KCL as necessary. Release packer. TOOH with packer and tubing.
- 8. Perforate 9612-9679', acidize as necessary for production.
- 9. Swab test/pump test.
- 10. Place well into production.

Rusty Klein

Agent for Threshold Development Company July 30, 2002