

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

RECEIVED

MAY 10 1982

O. C. D.
ARTESIA. OFFICE

Form C-103
Revised 10-1-7

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-8096	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
Name of Operator		8. Farm or Lease Name	
Marbob Energy Corp. /		Gray	
Address of Operator		9. Well No.	
P.O. Dr. 217, Artesia, N.M. 88210		1	
Location of Well		10. Field and Pool, or Wildcat	
UNIT LETTER A 330 FEET FROM THE North LINE AND 330 FEET FROM THE East LINE, SECTION 9 TOWNSHIP 19S RANGE 29E N.M.P.M.		Turkey Track SR-Q-G	
15. Elevation (Show whether DF, RT, GR, etc.)		12. County	
3397' GR		Eddy	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
REPAIR OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4/ 2/82

We plugged and abandoned this well as follows: Loaded hole w/mud, set a 35 sack plug and tagged @ 2602', set 25 sack plug @ 2500', set 25 sack plug @ 1700', cut off 5 1/2" casing @ 710', set 35 sack plug at top of casing, set 35 sack plug @ 300' and tagged, set 25 sack plug @ surface, set dry hole marker, moved battery equipment, cleaned location.

I, I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Michael J. Smith TITLE Production Clerk DATE 5/4/82

APPROVED BY Michael Smith TITLE OIL AND GAS INSPECTOR DATE JUN 11 1982

CONDITIONS OF APPROVAL, IF ANY: