

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-34647 RECEIVED

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

N/A FEB 5 1980

7. UNIT AGREEMENT NAME

N/A O. C. D.

8. FARM OR LAND OFFICE

CHARLOTTE MCKAY FEDERAL

9. WELL NO.

1

10. FIELD AND POOL OR WILDCAT

WILDCAT

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

SEC 25, 20S, 24E

12. COUNTY OR PARISH 13. STATE

EDDY

NEW MEXICO

SUNDRY NOTICES AND REPORTS **RECEIVED**(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL ☐ GAS ☒ OTHER ☐
WELL WELL

FEB 4 1980

2. NAME OF OPERATOR

SUN OIL COMPANY (DELAWARE)

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

3. ADDRESS OF OPERATOR

P.O. BOX 30, ROOM 3017; DALLAS, TX 75221

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FNL and 660' FEL

14. PERMIT NO.

30-015-23095

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3575' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☒
☒

PULL OR ALTER CASING

☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☐
☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Move in completion rig about February 5, block squeeze producing zones if required, perforate for production test 8884'-88', 8936'-48', and 8989'-94'. Clean the perforations with 2500 gallons 7-1/2% mud acid. Test the zone. If warranted, fracture the zones with about 20,000 gallons of weak acid gelled water carriers with 35,000 pounds of 20/40 sand proppant. No combustibles or hydrocarbons will be used.

Complete well through 2-7/8" tubing with packer.

Verbal to Ray Stall.

18. I hereby certify that the foregoing is true and correct

SIGNED

D. R. APTIN

(This space for Federal or State office use)

Professional Operations

TITLE Engineer

DATE January 30, 1980

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.