

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPlicate
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
LC-029392 B
6. IF INDIAN, ALLOTTEE OR TRUST NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

AUG 06 1984

O. C. D.
ARTESIA, OFFICE

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Hinkle "B" Federal
9. WELL NO.

10. FIELD AND FOOT, OR WILDCAT
11. SEC., T., R., OR B.L. AND SURVEY OR AREA

Shugart-7-SR-Q-6

Corrected copy
Sec. 22-18S-31E

12. COUNTY OR PARISH 13. STATE
Eddy N.M.

1. OIL ☐ GAS ☐ WELL ☒ OTHER

2. NAME OF OPERATOR
Westall - Mask

3. ADDRESS OF OPERATOR
P.C. Drawer 1477 Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also page 17 below.)
At surface

990' FEL and 330' FSL

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, CR, etc.)

3649.9 gr

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ FULL OR ALTER CASING ☐
FRACTURE TREATMENT ☒ MULTIPLE COMPLETE ☐
SHOOTING OR ACIDIZING ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANS ☐
(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☒ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☐
(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

We propose to do the below described work on May 28, 1984

We propose to frac the Queen 3708' to 3926'

We propose to set retrievable plug at 3650'

Perforate 32 holes

3708-20(7) 3738-54(9) 3818-22(3) 3882-90(5) 3912-26(8)

60,000 gallons gelled water & KCL

60,000# 20/40 sand

750 gallons acid

gyp control (tretolite)

use 2 3/8 or 27/8 ball sealers (20)

original total depth 4200'

18. I hereby certify that the foregoing is true and correct

SIGNED *[Signature]*

TITLE Trustee of the Jack Mask Trust 5-26-84

(This space for Federal or State office use)

APPROVED BY *[Signature]*

TITLE P.E.

DATE 5-22-84

CONDITIONS OF APPROVAL, IF ANY: