	Submit 3 Copies To Appropriate District	State	of Nour M	aviao - \	S	г	C 102
	Office	State of New Mexico Energy, Minerals and Natural Resources			Ϋ́́Ω		Form C-103 March 25, 1999
	District I Ellergy, White als and Natural Resources 1625 N. French Dr., Hobbs, NM 88240				WELL API NO.		
	District II	OIL CONSERVATION DIVISION			30-015-23258		
	District III 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505				5. Indicate Type of Lease		
					STATE 🖾 FEE 🗔		
	Entre Carlo				6. State Oil & Gas Lease No.		
	87505 SUNDRY NOTICES AND REPORTS ON WELLS				L-6287 7. Lease Name or Unit Agreement Name:		
	(DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOIR USE "APPLIC PROPOSALS.) 1. Type of Well: Oil Well Gas Well [2. Name of Operator Yates Petroleum Corpor 3. Address of Operator 105 South Fourth St 4. Well Location Unit Letter E : Section 12	ALS TO DRILL OR TO DE CATION FOR PERMIT (FO Deter Plug ration - Artesia, NM 8 2310 feet from th Township 10. Elevation (Show 360	eepen or pl orm C-101)F g & Aband 38210 he North 19S Ra w whether D. 03' GR	UG BACK TO A OR SUCH on line and 9 ange 24E R, RKB, RT, GR, etc.,	Irish Hills 8. Well No. 4 9. Pool name or V Penasco Draw 90 feet from NMPM Edd	Yeso JE S Wildcat San Andre Ass m the y County	s Yeso
-	11. Check A	ppropriate Box to I	ndicate N	ature of Notice, R	eport or Other I	Data	
				SUBS REMEDIAL WORK			: CASING 🗆
				COMMENCE DRIL	DRILLING OPNS. DPLUG AND ABANDONMENT		
-	PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AND CEMENT JOB			
	OTHER:			OTHER:			
	12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.						
	4-12-2002 - Moved in and rigged up pulling unit and plugging equipment. POOH with rods						
Post PrA	and pump. Shut well in for night. 4-13-15-2002 - Opened up well. Nippled down wellhead and nippled up BOP. Rigged up floor and 2-3/8" tubing equipment. POOH with 2-3/8" tubing. Shut well in for night. 4-16-2002 - RIH with CIBP on tubing to 2319'. Circulated hole with plugging mud. Spotted 25 sacks Class C Neat cement from 2319-1957'. POOH to 1791'. Spotted 25 sacks Class C Neat cement from 1791-1492'. POOH to 957'. Spotted 25 sacks Class C Neat cement. POOH with tubing. WOC 4 hours. RIH and tagged cement at 675'. POOH with tubing. Shut well in for night.						
los-	4-17-2002 - Opened up well. Nippled down BOP. RIH with tubing to 415'. Circulated 40 sacks Class C Neat cement from 415' to surface. POOH with tubing. Rigged down tubing equipment and floor. WOC 2 hours. Cement at 30'. Topped off with 10 sacks Class C Neat cement. Rigged down pulling unit and plugging equipment. Installed regulation abandonment marker. <u>PLUGGED AND ABANDONED - FINAL REPORT</u> . Plugging completed 4-16-2002.						
•	hereby certify that the information above is true and complete to the best of my knowledge and belief.						
	SIGNATURE Kusty L		_TITLE_A	gent for BCM &	Associates	_DATE <u>4-</u> 1	9-2002
	Type or print name Rusty Klein Telephone No. 746-6565						
-	(This space for State use)	OC)	* **	J. W. R.	0 P	MAY	9 2002
	APPPROVED BY	ft	_TITLE	June 19		_DATE	v 2 002
	Conditions of approval, if any:						