

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVING
OFFICE FOR NUMBER
OF COPIES REQUIRED
(Other instructions on re-
verse side)

BLM Roswell District
Modified Form No.
NMO60-3160-4

CLSF

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER CONVERT TO SWD - ORDER #370		5. LEASE DESIGNATION AND SERIAL NO. NM 36500	
2. NAME OF OPERATOR YATES PETROLEUM CORPORATION ✓		3a. Area Code & Phone No. 505/748-1471	
3. ADDRESS OF OPERATOR 105 South 4th St., Artesia, Nm 88210		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 810' FNL & 2180' FWL, Sec. 14-T19S-R25E		8. FARM OR LEASE NAME Cotton MX Federal	
14. PERMIT NO. 30-015-23315		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3430' GR		10. FIELD AND POOL, OR WILDCAT Boyd-Canyon	
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Unit C, Sec. 14-19S-25E	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)		12. COUNTY OR PARISH Eddy	
		13. STATE NM	

RECEIVED

MAR 14 '90

C. C. D.

ARTESIA, OFFICE

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANS ☐
(Other) Convert to SWD ☒

WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☐
(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

Propose to convert this well to a Salt Water Disposal well as follows. Pull sub-pump. GIH w/tubing and packer. Pump 2000 gals Temblock w/3-day breaker into perforations 7688-93' (and sand jet cuts @ 7689 & 91'). Wait on Temblock. POOH w/tubing and packer. GIH w/bit and collar and drill retainer at 7710 and squeeze perfs at 7716'. Clean out to 7930±. Will not drill retainer at 7960'. Perforate 7689-7915' w/58 - .42" holes. Acidize perforations in three stages w/5000 gals acid. Pull tubing and tools. Acidize down casing with 20000 gals 20% NEFE + block and ball sealers.

Approved for Salt Water Disposal by NMOCD Order No. SWD-370.
Form 299 has been previously filed with Bureau of Land Management.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature]

TITLE Production Supervisor

DATE 2-26-90

(This space for Federal or State office use)

APPROVED BY [Signature]
CONDITIONS OF APPROVAL, IF ANY:

TITLE [Signature]

DATE 3-12-90

By [Signature]

*See Instructions on Reverse Side