NO. OF COPIES RECEIVED			Form C-103
DISTRIBUTION			Supersedes Old C-102 and C-103
SANTA FE NEW MEXICO OIL CONSERVATION COMMISSION			Effective 1-1-65
FILE			
U.S.G.S.			5a. Indicate Type of Lease
LAND OFFICE			State X
			5. State Oil & Gas Lease No.
OPERATOR			LG-2725
			10-2123
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)			
1.		KECEIVED	7. Unit Agreement Name
OIL GAS X	OTHER.		
2. Name of Operator		1111	8. Farm or Lease Name
Southland F	Royalty Company	JUL 7 1980	State "A" 32
3. Address of Operator	byarey company		9. Well No.
<u>-</u>	Midland Moyag 70701	O. C. D.	1
1100 Wall Towers West,	Midiald, lexas 79701	ARTESIA, OFFICE	-
4. Location of Well		THE SIA, OFFICE	10. Field and Pool, or Wildcat
UNIT LETTER J . 19	980 FEET FROM THE SOUTH	LINE AND 1980 FEET FRO	(Morrow) Undesignated Winchester
east	N 32 TOWNSHIP 19-S	28-E	
THE <u>east</u> LINE, SECTION	TOWNSHIP TOWNSHIP	RANGE ZO-E NMPH	<u> </u>
	15. Elevation (Show whether	DF RT GR etc.)	12. County
	3365.3'	Gr.	Eddy ()
16. Check A	ppropriate Box To Indicate N	lature of Notice, Report or O	ther Data
NOTICE OF IN			IT REPORT OF:
		30501401.	THE OIL OIL
			. —
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
		other <u>Set 11 3/4"</u>	Surface Casing X
OTHER			
			_
	rations (Clearly state all pertinent deta	ails, and give pertinent dates, including	ng estimated date of starting any proposed
work) SEE RULE 1103.	~		
G. 1.15H. 1. 1. 0.2.00 PM C. 22.00 PM 21.1 15H hala ta 225H GCM to man one. DOOH			
Spud 15" hole @ 3:00 PM 6-22-80. Drill 15" hole to 335'. CCM to run csg. POOH.			
Ran 9 joints of 11 3/4" 42# H-40 ST&C casing (337'), set @ 335'. Cmt w/325 sxs			
class "C" w/2% C.C. PD @10:25 PM 6-22-80. Circ. 125 sxs. Cut off 11 3/4" csg.			
Install 11 3/4 X 12" 3000# Csg head. Install BOP. WOC 18 hr. Nipple up on BOP.			
After 24 hrs. pressure test BOP & 11 3/4" csg. to 1000# for 30 minutes. Held Okay.			
Drill ahead w/ll" bit.			
	t		
			•
	. # ∀.		
		•	
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
1) - 1 100		and all Oncorrelation The observer	7.1.00
SIGNED PURALO IX CA	TITLE DIST	rict Operation Engineer	C DATE 7-1-80
, ~			
		II AND CAD SESSIOTOS	JUL 8 1980
APPROVED BY _ ///// // //	Mama TITLE	IL AND GAS INSPECTOR	JUL 8 1980
	1116		
CONDITIONS OF APPROVAL, IF ANY:			