

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

RECEIVED

OCT 11 1993

WELL API NO. 30-015-23353
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Rio Penasco KD Com
8. Well No. 2
9. Pool name or Wildcat Boyd Morrow

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South Fourth Street - Artesia, NM 88210	4. Well Location Unit Letter F : 1680 Feet From The North Line and 1980 Feet From The West Line Section 2 Township 19S Range 25E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Abandon perfs & acidize existing perfs <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Moved in and rigged up pulling unit. Bled well down. Loaded annulus with KCL water. Loaded tubing. Released packer. Strip on BOP. TOOH w/packer and Vann guns. TIH with retrieving tool and washed 1' of fill off of packer. Latched on and released packer. TOOH w/packer and tubing conveyed guns. TIH w/retrieving tools and latched onto packer at 9082'. Released on/off tool. Washed off. Latched onto packer. Pulled up to equalize tool. Released packer at 9082'. TOOH. Packer hung up at 1800'. Worked loose. Laid down tubing conveyed guns. Ran 4.50" gauge ring and junk basket to 9100'. Set CIBP at 9050'. Capped with 35' of cement. TIH w/5-1/2" 17-20# 10K Uni VI packer with 1.87" XL on/off tool and set at 8800'. Nippled down BOP. Nippled up tree and made swab runs. Acidized perforations 8902-9005' with 3000 gallons 7-1/2% Morrow acid with 1000 scf/bbl nitrogen. Flowed well back and swabbed. Shut well in.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE Oct. 8, 1993
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505-748-1471

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

OCT 19 1993