THE RY	
RECEIVED BY NM OIL CONS. COMMIS: Drawer DD Artesia; NM 83210	SI
Dec 1973	Budget Bureau No. 42–R1424
OFFICE	5. LEASE
	<u>LC-029392B</u>
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Po not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME
reservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME Greenwood
1. oil gas 🛛 well 🖾 other	Pre-Grayburg Unit Fed "F" Fag
2. NAME OF OPERATOR	1 9. WELL NO.
Amoco Production Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Shugart_Penn
P. O. Box 68, Hobbs, New Mexico 88240 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
below.) AT SUBFACE: 10001 EST V OGOL EWI Unit 1	26-18-31
AT SURFACE: 1980' FSL X 860' FWL, Unit L AT TOP PROD. INTERVAL: Sec. 26, T-18-S, R-31-E AT TOTAL DEPTH:	12. COUNTY OR PARISH 13. STATE Eddy NM 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.	14. AFI NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 3651.8' GL
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT OFF	(NOTE: Report The of multiple completion or zone change of form 9-330.) APR A 1983
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stat including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner	te all pertinent details, and give pertinent dates, directionally drilled, give subsurface locations and
Moved in service unit 12-22-82. Remove tree a released packer. Finished pulling tubing, pac bridge plug set at 11609', packer set at 11485 Acidize and perforate at 11540'-49' with 1000 bbl of nitrogen 2. Flush with 44 bbl. 10# BW of gas. Ran tubing and retrievable bridge plu 11370' and packer set at 11305'. Ran swab 7 H and perforate 11396'-412' with 1000 gal 7-1/29 10# brine. Ran swab. Release packer, ran tub Swab tested 24 hours. Moved out service unit line. Shut-in. Flowing 16 BO, 85 BC, 33 BF, Open tubing to atmosphere. No gas flow. Ran equipment 3-15-83 and shut-in. Ran swab. Lig	and install blowout preventer and cker and tailpipe. Retrievable 5', and tailpipe set at 11516'. gal 7-1/2% HCL NEFE and 1000 SCF and 2% KCL. Ran swab. Good show ug set at 11502', tailpipe set at hours. Good show of gas. Acidize % HCL. Flush with 46 bbl 2% KCL bing and 2-3/8" seating nipple. 1-21-83. Re-connect to gas sales 518 BW and 9493 MCFin 264 hours. swab. Install plunger lift ght show of gas. Currently flow tes
() ()	1-F. J Nash 1-SUSP@1-PJSFt. ir
18. I hereby certify that the foregoing is true and correct	

SIGNED Filty Jema	TITLE AST. Adm.	Analyst DATE 3-30-83
0	(This space for Federal or Sta	ite office use)
APPROVED BY	TITLE	ACCEPTED FOR RECORD
	*See Instructions on Pau	SEP 0 9 1983

*See Instructions on Reverse Side

and a state of the state of the

.

•