

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

ENERLOC RESOURCES, INC.

3. Address and Telephone No.

PO BOX 1375 ROSWELL, NM 88202-1375

505/ 625-2060

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1984/5 ~~SEC.~~ & 860' FWL (UNIT LETTER L)

SEC. 26, T18S-R31E

RECEIVED

APR 09 1996

OIL CON. DIV.

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☒ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other _____
- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

03/12/96 Move in Mayo Marrs Casing Pulling, Inc. Take tree off and nipple up B.O.P. Could not get packer to release. On-off tool would not release. Ran ring to 12,275'. S.I. (Jim Amos of Carlsbad B.L.M. notified)

03/13/96 Ran in hole with 1 13/16" ceramic cutter and cut 2 3/8" off at 10,275'. Trip out of hole. Picked up 7 5/8" C.I.B.P./S.I. due to high winds.

03/14/96 Finish running tubing and set C.I.B.P. at 10,270' Spot 10 sack plug. Circulate 10# mud to 4,500'. Left tubing at 4,500' and S.I. due to high winds. (Don Early with B.L.M. on location)

03/15/96 Trip out of hole with tubing. Could not move 7 5/8" casing. Ran in hole with 6 3/8" jet cutter and cut casing at 4455'. Could not move casing or pump in. Cut window in 10 3/4" casing and found cement. Notify B.L.M. in Carlsbad. Trip in hole and set 25 sack cement plug from 4400 to 4500'. Shut down. Took head off and found cement between head and 7 5/8"

14. I hereby certify that the foregoing is true and correct

Signed

Title

President

Date

03/24/96

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title