

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
Collier Energy, Inc.

3. ADDRESS OF OPERATOR
P. O. Box 798, Artesia, NM 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
1980' FSL and 990' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3461' Grd.

5. LEASE DESIGNATION AND SERIAL NO.
NM-12111

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Toga Federal

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT
Wildcat-Queen

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
S15-T19S-R27E

12. COUNTY OR PARISH
Eddy

13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Existing Casing: 279' of 8 5/8" circulated to surface. 1313' of 4 1/2" cemented with 300 sxs. Squeezed from 1250' to surface.

Existing Perforations: 1180'-1205' with 4 shots.

Proposed Plugging Procedure: Set retrievable plug approximately 100' above existing perforations. Spot 25 sxs. on top of plug. 25 sxs. plug from 850'-550'. 100 foot plug from 329'-229'. 10 sxs. surface plug. Install marker.

RECEIVED
JUL 7 11 07 AM '88
CARLETON
AREA
OFFICE

18. I hereby certify that the foregoing is true and correct

SIGNED

Bucky Olson

TITLE

Agent

DATE 7-6-88

(This space for Federal or State office use)

APPROVED BY

WING. SEC. BALCH

TITLE

DATE

7-20-88

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side