UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

NM	OIL	CONS	COMMISSION
Dra	wer	DD	
	- 1		ECRIM-ADDDOVED

Artes ia, NM BELYOPROVED Budget Bureau No. 1004-0135

Expires: March 31, 1993

5. Lease Designation and Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS

NM 12264 86028 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE RECEIVED 1. Type of Well SCR 451 Oil Gas Well U Other 8. Well Name and No. 2. Name of Operator JUN - 7.'94 Lake McMillan Federal #1 <u>Barbara</u> Fasken 9. API Well No. 3. Address and Telephone No 30-015-23452 10. Field and Pool, or Exploratory Area
East Lake McMillan (Wolfcam
McMillan-Atoka, Southwest 303 W. Wall, Suite 1900, Midland, TX 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1450' FSL, 150' FEL 11. County or Parish, State Unit I, Sec. 30, T19S, R27E Eddy, NM

TYPE OF SUBMISSION	TYPE OF	TYPE OF ACTION			
Notice of Intent Subsequent Report Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water			
Describe Proposed or Completed Operations (Clearly		(Note:			

give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Propose to plug and abandon well as follows: (current wellbore diagram attached).

- POW $w/5\frac{1}{2}$ " pkr. and 2-3/8" tubing.
- Set $5\frac{1}{2}$ " CIBP on wireline @ 9386 $^{\circ}$. Dump 4 sx Class "H" cmt. on CIBP w/dump bailer. 2.
- Set $5\frac{1}{2}$ " CIBP on wireline @ 7820'. 3.
- RIW w/tbg. and displace well w/9 ppg brine w/25#/bbl. gel. Spot 10 sx Class "H" @ 7820'. POW w/tubing.
- Freepoint $5\frac{1}{2}$ " csg., cut off and recover estimated 7000' of casing.
- Spot Class "C" plugs as follows: (s.w. 14.8 ppg, yield 1.32 cuft/sx) a. 20 sx @ 7050' (50' inside $5\frac{1}{2}$ " stub). Tag this plug.

 - 30 sx @ 5140'.
 - 30 sx @ 2775'-2675' (8-5/8" shoe plug). Tag this plug.
 - 30 sx @ 370'-270' (13-3/8" shoe plug).
 - e. 15 sx @ 55' surface plug
- 7. Cut off casing 3' below ground level and erect marker.
- Remove all equipment, rip and reseed location with BLM approved seed.

(This space for Federal or State office use) (ORIG. SGD.) JOE G. LARA			Date _	<u> </u>	=
. I hereby certify that the foregoing is true and correct Signed	itle	Petroleum Engineer	Date	5-11-94	

attached

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.