**Submit 3 Copies** to Appropriate District Office District I P.O. Box 1980, Hobbs, NM 88240 District II

P.O. Box 1980, Hobbs, NM 88240

State of New Mexico gy. Minerals and Natural Resources Department

- 23469

## **OIL CONVERSATION DIVISION** P.O. Box 2088

Santa Fe, New Mexico 87504-2088

rorm	1 C-1	03	, 4,
Revi	sed 1	03  -1- <b>8</b> 9	U

WELL API NO.

5. Indicate Type of Lease

30

- 015

PLUG AND ABANDONMEN

<u>District III</u> P.O. Box 1980, Hobbs, NM 88240	STATE X FEE	
1.0. DOX 1980, 110003, NM 60240	6. State Oil & Gas Lease No. B8944	
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMECEIVED  (FORM C-101) FOR SUCH PROPOSALS.)	7. Lesse Name or Unit agreement Name	
1. Type of Well: OIL GAS X OTHER  1. Type of Well: OIL GAS X OTHER	STATE CZ	
2. Name of Operator OXY USA INC.  ARTESIA OFFICE	8. Well No.	
3. Address of Operator P.O. Box 50250 Midland, TX 79710	9. Pool name or Wildcat TURKEY TRACK MORROW, NO.	
4. Well Location  Unit Letter H : 2,180   Feet From The NORTH   Line and 960		
Section 4 Township 19 S Range 29 E	NMPM EDDY County	
10. Bevation (Show whether DF, RKB, RT, GR, etc.) 3,214		
11. Check Appropriate Box to Indicate Nature of Notice, Repo	rt, or Other Data	
NOTICE OF INTENTION TO: SUBSE	QUENT REPORT OF:	
PERFORM REMEDIAL WORK X PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING	

COMMENCE DRILLING OPNS.

CASING TEST AND CEMENT JOB

12. Describe Proposed or Complete Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any work) SEE RULE 1103.

TD - 11500' PBTD - 11453' PERFS - 11340' - 11345

1) MIRU PU. KILL WELL W/ 2% KCL WTR. NDWH, NUBOP. TOOH W/ TBG..

**CHANGE PLANS** 

2) RU WIRELINE AND SET CIBP @ 11330'.

OTHER: PERF ADD'L MORROW & ACIDIZE

**TEMPORARILY ABANDON** 

**PULL OR ALTER CASING** 

3) PERFORATE UPPER MORROW W/ 2 JSPF @ 11130,31,134-138,163-184,187-205,226-229,232-235,310-312,317-11325'. TOTAL OF 140 HOLES.

OTHER:

- 4) ACIDIZE MORROW (11130'-11325') W/ 6000 GAL 7-1/2% NeFe HCI ACID W/ FRIC. RED, CLAY STAB, 70-7/8" RCNBS & 1000 SCF N2 PER BBL. MAX PSI-8000#. SI WELL, OPEN WELL & RECOVER LOAD.
- 5) SI WELL FOR 72 HRS & RUN STATIC BHP TEST.

SIGNATURE	above is true and complete to the best of my knowled		Production Accountant	DATE 11 11 91	
TYPEORPHINT NAME David Stewart				TELEPHONE NO. 915 685-5717	
(This space for State Use)	ORIGINAL SIGNED BY MIKE WILLIAMS			NOU 0 6 4004	
APPROVED BY	SUPERVISOR, DISTRICT IN	TITLE		NOV 2 1 1991	