

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

+ c15P
up

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

RECEIVED

MAR 31 1993

WELL API NO. 30-015-23540
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Davis NC Com
8. Well No. 1
9. Pool name or Wildcat Boyd Morrow

SUNDRY NOTICES AND REPORTS ON WELLS.
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER WORKOVER

2. Name of Operator
YATES PETROLEUM CORPORATION

3. Address of Operator
105 South 4th St., Artesia, NM 88210

4. Well Location
Unit Letter I : 1980 Feet From The South Line and 660 Feet From The East Line

Section 11 Township 19S Range 24E NMPM Eddy County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3602' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: Add pay in Morrow, acidize & frac <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well completed in Morrow perforations 8704-8820'. Propose to add pay in the Morrow 8761-8766' as follows:

- 1) POH w/production tubing and two Uni VI packers.
- 2) RIH w/casing gun and perforate 8761-8766' (2 SPF).
- 3) RIH w/RBP, packer and 2-7/8" workstring.
- 4) Isolate and break down new perfs 8761-8766' w/1500 gals 7 1/2% acid and 10 balls.
- 5) Move RBP to below bottom perf at 8820'. PUH w/packer to \pm 8650'.
- 6) Frac all Morrow perfs (8704-08', 8761-66', 8816-20') w/42000 gals 70 Q Foam & 42000# 20/40 RC sand.
- 7) Swab well in as necessary and turn well to production.

3-30-93. Verbal permission obtained from Mr. Mike Williams, NMOCD, Artesia, NM, to begin work.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 3-30-93
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

APPROVED BY _____ DATE MAR 31 1993

CONDITIONS OF APPROVAL, IF ANY: