Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Energy, Minerals and Natural Resources Departmen

| District Office | 1 |
|---|---|
| DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION P.O. Box 2088 | WELL API NO. |
| DISTRICT II Santa Fe, New Mexicon 27504 2988 P.O. Drawer DD, Artesia, NM 88210 | 5. Indicate Type of Lease STATE FEE X |
| DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 | 6. State Oil & Gas Lease No. |
| SUNDRY NOTICES AND REPORTS ON WELLS A COMMENT OF THE PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | 7. Lease Name or Unit Agreement Name |
| 1. Type of Well: OIL GAS WELL X WELL OTHER | Bradshaw |
| 2. Name of Operator | 8. Well No. |
| Anadarko Petroleum Corporation 3. Address of Operator | 9. Pool name or Wildcat |
| P.O. Drawer 130, Artesia, New Mexico 88211-0130 | Penasco Draw - Upper Penn. |
| 4. Well Location Unit Letter P: 660 Feet From The South Line and | 660 Feet From The East Line |
| Section 4 Township 19S Range 25E | NMPM Eddy County |
| Section 4 Township 193 Range 2.51 10. Elevation (Show whether DF, RKB, RT, GR, etc.) | |
| | |
| Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: | |
| PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK | ALTERING CASING |
| TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT | |
| PULL OR ALTER CASING CASING TEST AND | <u></u> |
| Additional parfe & acidize X outen | |
| | |
| 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, in work) SEE RULE 1103. | cluding estimated date of starting any proposea |
| Rig up pulling unit; install BOP. Pull rods & tubing. Perforate additional Cisco Canyon zone (7864 Canyon perfs: (7758'-70') & (7788'-94'). Straddle & acidize new perfs (7864'-68'); sw Straddle & acidize old perfs (7758'-94' OA); Pull packer & retrievable bridge plug. Run tubing & rods. Remove BOP & rig down pulling unit. Return to pump. | ab test. |
| I hereby certify that the information above is true and complete to the best of my knowledge and belief. Area | Supervisor 01-22-92 |
| SIGNATURE SIGNATURE Area | DATE |
| TYPE OR PRINT NAME | TELEPHONE NO. |
| (This space for State Use) ORIGINAL SIGNED BY MIKE WILLIAMS | JAN 2 9 1992 |
| SUPERVISOR, DISTRICT 19 TIME | DATE - |

CONDITIONS OF AFFROVAL, IF ANY: