

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-015-23564

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER ☐

RECEIVED

2. Name of Operator

YATES PETROLEUM CORPORATION

AUG 15 '94

3. Address of Operator

105 South Fourth Street - Artesia, NM 88210

O. C. D.

4. Well Location

ARTESIA, OFFICE

Unit Letter P : 660 Feet From The South Line and 660 Feet From The East Line

Section 4

Township

19S

Range

25E

NMPM

Eddy

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3517.9' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Fish tubing ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-3-94 - Moved in and rigged up pulling unit. Nippled down wellhead and installed BOP. Picked up on overshot. Latched onto fish at 2745'. Pulled 38000# and tubing jumped. TOOH and laid down 6 joints of 2-3/8" N-80 tubing below overshot. TIH w/6-1/2" impression block and 2-3/8" tubing to casing stub at 2604'. TOOH. Impression block showed casing stub to be 4-1/2" OD and in good shape. Clean and drift 4-1/2" 10.5# J-55 casing. Rigged up casing crew and ran 6-1/2" X 4-1/2" packed off overshot and 58 joints of 4-1/2" 10.5# J-55 casing. Latched onto casing stub at 2604' with overshot. Pulled tension in casing to 30000#, 3000# over string weight. Set slips in casing. Made cut off on 4-1/2" casing and installed casing head and BOP. TIH with 3-7/8" overshot and 2-3/8" tubing to tubing fish at 2936'. Latched onto tubing fish with overshot and pull tension in tubing to 45000#, 8000# over string weight. Rigged up wireline. TIH with free point tool - could not get down past 8645'. Free point shows tubing to be stuck from 8645' down. TOOH with free point tool. TIH w/jet cutter and cut tubing off at 8620'. Tubing came free. TOOH with jet cutter and rig down wireline. TOOH with 2-3/8" tubing. Laid down 184 joints of 2-3/8" N-80 tubing and 20' cut off piece of tubing below overshot. Rig up wireline. TIH w/logging tools.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Rusty Klein

TITLE

Production Clerk

DATE 8-10-94

TYPE OR PRINT NAME

Rusty Klein

505-748-1471
TELEPHONE NO.

(This space for State Use)

SUPERVISOR, DISTRICT II

AUG 19 1994

APPROVED BY

TITLE

DATE