

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

NOV 2 '94

WELL API NO. 30-015-23636
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG-3998
7. Lease Name or Unit Agreement Name Hogback PO State Com
8. Well No. 1
9. Pool name or Wildcat Undesignated

SUNDRY NOTICES AND REPORTS ON WELLS - C. D. (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator YATES PETROLEUM CORPORATION	
3. Address of Operator 105 South Fourth Street - Artesia, NM 88210	
4. Well Location Unit Letter C : 660 Feet From The North Line and 1980 Feet From The West Line Section 20 Township 19S Range 24E NMPM Eddy County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3764' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-20-94 - Moved in and rigged up pulling unit.

10-21-94 - Circulated well with brine water. Nippled down wellhead. Nippled up BOP. POOH with 2-3/8" tubing. Ran dump bailer & weight bars with 3-1/2" OD. Tagged at 1800'. POOH & laid down bailer and tools. Rigged down wireline. Picked up bit and bit sub. RIH with 2-3/8" tubing. Closed BOP. Opened on a 1/4" choke. Left flowing overnight.

10-22-24-94 - Picked up and RIH with 2-3/8" tubing to 6048'. Reverse circulate clean with 120 bbls brine water. POOH with tubing. RIH and set 4-1/2" CIBP at 6025'. RIH with tubing and tagged CIBP at 6025'. Spot 37 bbls plug mud from 6025-3725' in 4-1/2" casing. Spot 25 sacks Class C from 6025-5650' in 5-1/2" casing. POOH with tubing to 5000'. Spot 25 sacks Class C from 5000-4630' in 4-1/2" casing. POOH with tubing to 2200'. Shut in overnight.

10-25-94 - POOH & laid down 2-3/8" tubing. Rigged up wireline. RIH and set 4-1/2" CIBP at 3725'. RIH with tubing and tag CIBP at 3725'. Spot 57 bbls plug mud from 3725' to surface. Spot 25 sacks Class C cement from 3725-3350'. POOH with tubing to 1800'. Spot 25 sacks Class C from 1800-1425' in 4-1/2" casing. POOH and laid down excess tubing. Picked up 4-1/2" packer. RIH with 2-3/8" tubing. Found casing leak. 4-1/2" casing is communicating

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Rusty Klein*

TYPE OR PRINT NAME Rusty Klein

TITLE Production Clerk

DATE 10-28-94

505-748-1471
TELEPHONE NO.

CONTINUED

(This space for State Use)

APPROVED BY *Tracie Stalder*

TITLE Field Rep. I

DATE April 18-95