lubmit 3 Copies o Appropriate		New Mexico nural Resources Department	Form C-103 Revised 1-1-89	-1>1' M
District Office DISTRICT 1 9.0. Box 1980, Hobbs, NM 88240	P.O. I	ATION DIVISION Box 2088	WELL API NO. 30-015-23682	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New N	Aexico 87504-2088	5. Indicate Type of Lease STATE X FEE	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No. LG-2040	
	ICES AND REPORTS	N WELLS		\overline{M}
(DO NOT USE THIS FORM FOR PR	ROPOSALS TO DRILL OR TO ROPOSALS TO DRILL OR TO ROVOR. USE "APPLICATION C-101) FOR SUCH PROPOSA	FOR PERMIT"	7. Lease Name or Unit Agreement Name	
I. Type of Well: OIL GAS WELL WELL X	.] отне я	MERCEIVE	New Mexico DB State Com	
2. Name of Operator			8. Well No.	
YATES PETROLEUM CORPOR	RATION	MAY 1 6 1996	9. Pool name or Wildcat	
3. Address of Operator 105 South 4th St., Ar	tocia NM 88210		N JUN Jundesignated Cisco	ļ
4. Well Location	Lesia, Mi 00210	OIL CON.		
	980_FeetFromThe_Nort		80 Feet From The West	Line
7	Township 19S	Range 24E		unty
Section /	Township 195	w whether DF, RKB, RT, GR, etc.)		$///\lambda$
		839' KB		
11. Check	Appropriate Box to In	ndicate Nature of Notice,	Report, or Other Data	
	NTENTION TO:	SU	JBSEQUENT REPORT OF:	
	PLUG AND ABANDO		ALTERING CASING	
	CHANGE PLANS			
PULL OR ALTER CASING		CASING TEST AND		
		OTHER: Recomp	lete to Cisco	X
			· · · · · · · · · · · · · · · · · · ·	
work) SEE RULE 1103. 5-7-96 - Moved in an down wellhead and in 5-8-96 - TIH with ga	nd rigged up pulli nstalled BOP. Uns auge ring and junk	ng unit. Loaded tu et packer. TOOH wi basket to 8200'.	bing with 2% KCL water. Nipp th tubing and packer. TOOH with gauge ring and junk BP with 35' of cement. Press	oled
test casing. Pumped to	d into casing leaf 650 psi in 10 mir	at 2 BPM at 900 ps nutes and held 650 p	i. After shut down, casing si for 20 minutes. TIH with tools and rigged down wirel	
test casing. Pumped pressure dropped to logging tools and r. Rigged up tubing te tubing testers. Sh 5-9-96 - Spot 500 g casing guns and per 84, 86, 6222, 24, 2 Cisco Lime). TOOH Acidized perforation	d into casing lear 650 psi in 10 min an CBL/CCL/GR log sters. Tested tub ut down. allons 20% iron co forated 6152-6362 6, 31, 33, 35, 37 with casing guns ons 6152-6362' wit	at 2 BPM at 900 ps nutes and held 650 p TOOH with logging oing in hole to 5000 ontrol acid at 6374' w/23 .42" holes as , 65, 67, 6317, 19, and rigged down wire h 4000 gallons 20% i	 i. After shut down, casing si for 20 minutes. TIH with tools and rigged down wirel psi to 6376'. Rigged down TOOH with tubing. TIH wi follows: 6152, 54, 56, 80, 21, 54, 56, 58 & 6362' (1 SP eline. TIH with packer and t 	ine. th 4" 82. F — ubing
test casing. Pumped pressure dropped to logging tools and r. Rigged up tubing te tubing testers. Sh 5-9-96 - Spot 500 g casing guns and per 84, 86, 6222, 24, 2	d into casing leaf 650 psi in 10 min an CBL/CCL/GR log. sters. Tested tub ut down. allons 20% iron co forated 6152-6362 6, 31, 33, 35, 37 with casing guns ons 6152-6362' wit	at 2 BPM at 900 ps nutes and held 650 p TOOH with logging oing in hole to 5000 ontrol acid at 6374' w/23 .42" holes as , 65, 67, 6317, 19, and rigged down wire h 4000 gallons 20% is knowledge and belief.	 i. After shut down, casing si for 20 minutes. TIH with tools and rigged down wirel psi to 6376'. Rigged down TOOH with tubing. TIH wi follows: 6152, 54, 56, 80, 21, 54, 56, 58 & 6362' (1 SP eline. TIH with packer and t CONTINUED ON NEXT PAGE: 	ine. th 4" 82. F - ubing ers.
test casing. Pumper pressure dropped to logging tools and r. Rigged up tubing te tubing testers. Sh 5-9-96 - Spot 500 g casing guns and per 84, 86, 6222, 24, 2 Cisco Lime). TOOH Acidized perforation I hereby certify that the information above it skonature	d into casing leaf 650 psi in 10 min an CBL/CCL/GR log sters. Tested tub ut down. allons 20% iron co forated 6152-6362 6, 31, 33, 35, 37 with casing guns ons 6152-6362' wit	at 2 BPM at 900 ps nutes and held 650 p TOOH with logging oing in hole to 5000 ontrol acid at 6374' w/23 .42" holes as , 65, 67, 6317, 19, and rigged down wire h 4000 gallons 20% i	 After shut down, casing si for 20 minutes. TIH with tools and rigged down wirel psi to 6376'. Rigged down TOOH with tubing. TIH wi follows: 6152, 54, 56, 80, 21, 54, 56, 58 & 6362' (1 SP eline. TIH with packer and t iron control acid & ball seal CONTINUED ON NEXT PAGE: n Clerk DATE May 15, 1 	ine. th 4" 82. F - ubing ers. 996
test casing. Pumped pressure dropped to logging tools and r. Rigged up tubing te tubing testers. Sh 5-9-96 - Spot 500 g casing guns and per 84, 86, 6222, 24, 2 Cisco Lime). TOOH Acidized perforation	d into casing leaf 650 psi in 10 min an CBL/CCL/GR log sters. Tested tub ut down. allons 20% iron co forated 6152-6362 6, 31, 33, 35, 37 with casing guns ons 6152-6362' wit	at 2 BPM at 900 ps nutes and held 650 p TOOH with logging oing in hole to 5000 ontrol acid at 6374' w/23 .42" holes as , 65, 67, 6317, 19, and rigged down wire h 4000 gallons 20% is knowledge and belief.	 i. After shut down, casing si for 20 minutes. TIH with tools and rigged down wirel psi to 6376'. Rigged down TOOH with tubing. TIH wi follows: 6152, 54, 56, 80, 21, 54, 56, 58 & 6362' (1 SP eline. TIH with packer and t CONTINUED ON NEXT PAGE: 	ine. th 4" 82. F - ubing ers. 996

١