


|                        |                                     |
|------------------------|-------------------------------------|
| NO. OF COPIES RECEIVED |                                     |
| DISTRIBUTION           |                                     |
| SANTA FE               | <input checked="" type="checkbox"/> |
| FILE                   | <input checked="" type="checkbox"/> |
| U.S.G.S.               | <input checked="" type="checkbox"/> |
| LAND OFFICE            | <input checked="" type="checkbox"/> |
| OPERATOR               | <input checked="" type="checkbox"/> |

NEW MEXICO OIL CONSERVATION COMMISSION



Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State ☒ Fee ☐  
5. State Oil & Gas Lease No.  
L-1493

SUNDY NOTICE AND REPORT OF OPERATIONS  
DO NOT USE THIS FORM FOR PROPOSED TO ABANDON OR TO PERFORM PLUG BACK TO A DIFFERENT RESERVOIR.  
SEE APPLICATION FOR PERMIT TO ABANDON (FORM C-101) FOR SUCH PROPOSALS.

|                                                                                                                                              |                                                         |
|----------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>                             | 7. Unit Agreement Name                                  |
| 2. Name of Operator<br>Southland Royalty Company                                                                                             | 8. Farm or Lease Name<br>Parkway "C" St Com             |
| 3. Address of Operator<br>21 Desta Drive, Midland, Texas 79705                                                                               | 9. Well No.<br>1                                        |
| 4. Location of Well<br>UNIT LETTER F 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 15 TOWNSHIP 19S RANGE 29E NMPM. | 10. Field and Pool, or Wildcat<br>Turkey Track (Strawn) |
| 11. Elevation (Show whether DF, RT, GR, etc.)<br>3339' GR                                                                                    | 12. County<br>Eddy                                      |

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

|                                                |                                           |                                                      |                                               |
|------------------------------------------------|-------------------------------------------|------------------------------------------------------|-----------------------------------------------|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/>               | ALTERING CASING <input type="checkbox"/>      |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>     | COMMENCE DRILLING OPS. <input type="checkbox"/>      | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/>  | OTHER <input checked="" type="checkbox"/> | CASING TEST AND CEMENT JOBS <input type="checkbox"/> |                                               |
| Abandon Atoka & recomplete in Strawn Zone      |                                           |                                                      |                                               |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pull tbg & Guiberson pkr.
2. Set a CIBP @ 10,690' & cap w/35' of cmt.
3. Run tbg & csg scraper to PBDT, Circ the hole clean w/treated 2% KCl wtr & pull the tbg.
4. Run 2 3/8" tbg, Guiberson uni pkr VI & 4" Vann System perforating gun.
5. RU Vann logging unit & run GR/CCL thru the tbg & space the gun to perforate from 10,440-452' & 10,496-10,502' w/4 JSPF.
6. Set the pkr & NUWH.
7. Drop detonating bar & fire the gun.
8. Open well to the pit & test.
9. If required, install tree saver & acidize w/3000 gal 7 1/2% HCl acid containing Morrow additives, 1000 SCF/Bbl N<sub>2</sub>, & friction reducer. Plug w/slick 2% KCl wtr containing clay control & N<sub>2</sub>.
10. Remove tree saver & flow the well back.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED \_\_\_\_\_ TITLE Operations Engineer DATE 2/11/85  
Original Signed By  
Leslie A. Clements  
APPROVED BY \_\_\_\_\_ TITLE Supervisor District II DATE FEB 12 1985  
CONDITIONS OF APPROVAL, IF ANY: