

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-015-23820

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

88096

7. Lease Name or Unit Agreement Name

Conoco 9A State

8. Well No.

1

9. Pool name or Wildcat

Turkey Tract Straw Gas

1. Type of Well:

OIL

WELL ☐

GAS

WELL ☒

OTHER ☐

2. Name of Operator

Threshold Development Co

3. Address of Operator

777 Taylor St., Ste II-D, Ft. Worth, TX 76102

4. Well Location

Unit Letter G : 1980 Feet From The North Line and 1980 Feet From The EAST Line

Section

9

Township

19 S

Range

29 E

NMPM

EDDY

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3413 KB

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

* see attached detailed report

Est ID -

6-5-98

P414

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

P.E.

DATE

5/21/98

TYPE OR PRINT NAME

Alan T. Davis

TELEPHONE NO.

817-870-1483

(This space for State Use)

APPROVED BY

Michael Stufflefield

TITLE

Field Rep. II

DATE

June 26 98

CONDITIONS OF APPROVAL, IF ANY:

Conoco 9A STATE "1"
Eddy County, New Mexico

DAILY WORKOVER REPORT

5/7/98

MIRN SIERRA Well Svc Kim well. NO wellhead, NO BOP'S
COULD NOT UNSEAT PER. Release tbg from pkr @ on-off tool.
POOH w/tbg. RTH w/ CIBP, set @ 10,236', dump 5 sx
cut on top. RTH w/ 57 stands tbg. SDFN

5/8/98

FINISH RTH w/tbg to 10,200'. Pump 125 bbls 9.5 ppg mud.
PUH to 9755', pump 25 sx plug. PUH to 8981', pump
25 sx plug. PUH to 6851', pump 25 sx plug. POOH w/12
stands. SDFWEND.

5/11/98

FINISH POOH w/tbg, lay down 116 jts, 202 jts in derrick.
Broke out 5 1/2" wellhead, pull stretch on 5 1/2" csg. Shoot off
5 1/2" csg @ 6326'. Start POOH w/csg laying down. SDFN

5/12/98

FINISH POOH w/5 1/2" csg. RTH w/tbg to 6375', set 50 sx plug.
POOH w/20 stands tbg, reverse tbg. WOC. TAG top of plug
@ 6174'. PUH w/tbg to 3050'. SDFN

5/13/98

Pump 50 sx plug from 3050-2950'. PUH & reverse out. WOC 4 hrs
TAG TOP OF PLUG @ 2890'. PUH to 385', pump 35 sx. PUH &
set 10 sx plug @ sfc. cut of csg, put up dry hole marker.
Well PA'd 5/13/98.