

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501
JUN 15 1984
O. C. D.
ARTESIA, OFFICE

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Ralph Nix ✓	8. Farm or Lease Name Debbie
3. Address of Operator P.O. Box 617, Artesia, New Mexico 88210	9. Well No. 1
4. Location of Well UNIT LETTER <u>I</u> , <u>660</u> FEET FROM THE <u>East</u> LINE AND <u>1980</u> FEET FROM THE <u>South</u> LINE, SECTION <u>11</u> TOWNSHIP <u>20S</u> RANGE <u>24E</u> N.M.P.M.	10. Field and Pool, or Wildcat Wildcat Canyon
15. Elevation (Show whether DF, RT, GR, etc.) 3608' GR	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1133.

Plugs:

#1 7725' CIBP W/35' cement cap
#2 7100' - 7200'
*#3 5400' - 5500' will verify
#4 4350' - 4450'
#5 2250' - 2350'
#6 1155' - 1255' will verify
#7 365' - 465'
#8 0' - 30'

Regulation surface marker to be set, mud between plugs at 10 sx per thousand feet.

*Note to plug #3 Intend to cut and pull 5½" casing at this point. Plug will be set 50' in and out of stub. Should free point not occur at this depth plug will be set 50' in and out at cut off depth.

Proposed plugging operation to start ASAP.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Ralph Nix Jr.

SIGNED Ralph Nix Jr. TITLE _____ DATE June 14, 1984

Original Signed By
Leslie A. Clements
Supervisor District II

APPROVED BY _____ TITLE _____ DATE JUN 18 1984

CONDITIONS OF APPROVAL, IF ANY:

Notify OCD 24hrs. prior to setting 1st plug.