

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED BY

AUG 13 1986

O. C. D.

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease

State ☐

Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR RE-ENTER OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER <u>Shut-in</u>	7. Unit Agreement Name
2. Name of Operator CONOCO INC.	8. Farm or Lease Name <u>Debbie</u>
3. Address of Operator P. O. Box 460, Hobbs, N.M. 88240	9. Well No. <u>1</u>
4. Location of Well UNIT LETTER <u>I</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>11</u> TOWNSHIP <u>20S</u> RANGE <u>24E</u> NMPM.	10. Field and Pool, or Wildcat <u>Wildcat Canyon</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>3608 GL</u>	12. County <u>Eddy</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- ① MIRU, Set CIBP @ 7700'. Spot 7 sxs class "H" cmt from 7650'-7700'.
- ② Spot 20 sxs class "H" cmt from 5450'-5600'. Perf @ 3350' w/4 JS PF.
- ③ Set cmt retainer @ 3340'. Attempt to establish circ. If circ. is established, pump 55 sxs class "H" cmt & displace all but 13 sxs. Spot the 13 sxs on top of retainer. (3240'-3340')
- ④ If a pump-in rate is not established, Pull out of retainer & spot ²⁵ 13 sxs from 3240'-3340'.
- ⑤ Perf @ 1250' w/4 JS PF. Attempt to establish circ. w/9.0 ppg mud. If circ. is established, pump 450 sxs class "H" cmt to surface.
- ⑥ If circ. cannot be established, engineer in the office will be contacted.
- ⑦ Cut off wellhead & install abandonment marker. Rig down
- ⑧ A P&A sketch is attached.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

Ken H. Vogel

TITLE

Administrative Supervisor

DATE

8-12-86

APPROVED BY

Mike Williams

OIL AND GAS INSPECTOR

Notify N.M.O.C.C. in sufficient time to witness

DATE

SEP 04 1986

CONDITIONS OF APPROVAL, IF ANY:

Plugging

NMCO-Artesia(3)